



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8122L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID COVER	TO REPAIR SEE LABOUR	2,480.40	-
1	REAR BUMPER ASSY	CUT	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER BEAM	SERVICEABLE	394.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	FOG LAMP	SERVICEABLE	201.50	-
1	ANTENNA ASSY-SMARTKEY	SERVICEABLE	40.50	-
1	BOOTLID EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	BOOTLID EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	BOOTLID EMBLEM-H	NECESSARY	28.00	28.00
	LESS 20% DISCOUNT		-826.69	-203.25
			3,306.76	813.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	ADVERTISEMENT LOGO-FENDER (SN)	NECESSARY	200.00	200.00
1	ADVERTISEMENT LOGO-BOOTLID (SN)	NECESSARY	100.00	100.00
1	REVERSE SENSOR (SN)	CUT	180.00	180.00
1	REAR BOOTLID COMFORT LOGO (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID TEL NOS LOGO (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID APPS LOGO (SN)	NECESSARY	40.00	40.00
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			676.00	630.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID COVER.		800.00	700.00
	SPRAY PAINT.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		50.00	20.00
	CHECK WIRING.		50.00	20.00

Report Ref No. NS/INC21013131/Vtcn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
			1,620.00	1,240.00
GRAND TOTAL			5,602.76	2,683.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,150.00

Report Ref No. NS/INC21013131/Vtcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.