



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

LKK-
QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: SMRT TAXIS PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Document No.	: SQT21003932	Page	1
Registration No	: SLH8853T	Date	: 22. Dec 2021	Customer No.	: WZS002
Chassis No	: JHMRU1810GX201141	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15B4531141
Model	: HRV DX-SIN CVT YM 2016	Date Time	: 22. Dec 2021 11:43:47 AM	Surveyor Name	:
Owner's Name	: CHOO HUI ZHEN, ALENE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 20/12/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHOO HUI ZHEN ALENE OWNER INSURER: TOKIO MARINE ACC DATE: 20/12/2021 SURVEYED BY: DATE: REF NO: TP INSURER: SMRT TP VEH: SHF337C						
04711-T7A-N00ZZ	FACE,FR.BUMPER <i>de</i>	1	507.10	25	380.32	26.62	406.94
71102-T7B-000	FACE FR. BUMPER LOWER <i>SCA</i>	1	374.40	25	280.80	19.66	300.46
71103-T7A-000	GRILLEFR.BUMPER <i>3 X AN</i>	1	84.20	25	63.15	4.42	67.57
71105-T7A-000	GARNISH,R.FR.FOG LIGHT <i>? X AN</i>	1	24.10	25	18.07	1.26	19.33
71140-T7A-000	BEAMR.FR.BUMPER UPPER <i>? X AN</i>	1	28.10	25	21.07	1.47	22.54
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE <i>acc</i>	1	11.70	25	8.77	0.61	9.38
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE <i>acc</i>	1	11.70	25	8.77	0.61	9.38
91505-TM8-003	CLIP,BUMPER <i>acc</i>	22	2.30	25	37.95	2.66	40.61
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER <i>? X AN</i>	1	237.80	25	178.35	12.48	190.83
60210-T7A-J00ZZ	PANEL COMP,R.FR.FENDER <i>repair</i>	1	421.10	25	315.82	22.11	337.93
74107-T7B-003	PROTECTOR,R.FR.WHEEL ARCH <i>SCA</i>	1	163.80	25	122.85	8.60	131.45
33100-T7S-E11	HEADLIGHT ASSY,R. <i>SCA</i>	1	1952.70	25	1464.52	102.52	1567.04
60400-T7A-901ZZ	BULKHEAD COMP,FR. <i>X AN</i>	1	463.30	25	347.47	24.32	371.79
	Sum Item				3247.91	227.34	3,475.25
BOSUN	SUNDRIES	1	50.00 <i>30</i>		50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00 <i>250</i>		280.00	19.60	299.60
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. <i>@650</i>	1	2600.00 <i>1300</i>		2600.00	182.00	2782.00

Printed on 27/12/2021 1:54:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Customer : SMRT TAXIS PTE LTD
 60 WOODLANDS INDUSTRIAL
 PARK E4
 SINGAPORE 757705

Registration No : SLH8853T

Chassis No : JHMRU1810GX201141

Model : HRV DX-SIN CVT YM 2016

Owner's Name : CHOO HUI ZHEN, ALENE

Ins Policy No. :

Date of Accident : 20/12/2021

Document No. : SQT21003932 Page 2

Date : 22. Dec 2021

Customer No. : WZS002

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L15B4531141

Date | Time : 22. Dec 2021 11:43:47 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) <i>@520</i>	1	3120.00		3120.00	218.40	3338.40
			<i>1560 /</i>	Sum Labor	<u>6050.00</u>	<u>423.50</u>	<u>6,473.50</u>

Survey By *Jasul - Hp 90010068*

Date & Time *04/01/22 @ 11:50*

Excess

Status

Signature

Sdays
Req before paint

[Signature]

Total Amount 9,297.91 650.84 9,948.75

Total (Inclusive of GST) 9,948.75

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 27/12/2021 1:54:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.