



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21013139/R1tf3n2	
			Date: 26/01/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHF 337C	Veh. Inspected	SLH 8853T
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/21/2046	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	27/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA HRV 1.5 DX CVT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHMRU1810GX201141	Colour	RED
	Odometer	93634 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	20/12/2021	Inspection Date	04/01/2022
	Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	