

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

*ms find
9/10/21
Kenneth
04/01/2022*

25/12/2021

Owner: NEU AIK HOU

ESTIMATE TO REPAIR HONDA VEZEL - SLR8313H

1pc front LH headlamp
1pc front LH headlamp lower bracket
1pc front bumper
20pcs front bumper clip @\$5.00
1pc front bumper grille
1pc front bumper lower lid
1pc front bumper LH side retainer
1pc front bumper LH fog lamp
1pc front bumper LH fog lamp base
1pc front bumper LH fog lamp garnish
1pc front centre grille base
1pc front centre grille outer garnish
1pc front wiper tank
1pc front LH fender protector

*NOT Authorised
11 Day @
Resurvey After Paint
2 day*

<i>MTCM</i>	\$ 1,759.40	✓
	\$ 45.00	X
<i>Bu</i>	\$ 927.50	✓
<i>Ma</i>	\$ 100.00	✓
<i>Pa</i>	\$ 195.20	X
<i>Pa</i>	\$ 485.50	X
<i>DIS</i>	\$ 38.10	✓
<i>Pa</i>	\$ 385.50	X
<i>Pa</i>	\$ 85.50	X
<i>Pa</i>	\$ 125.50	X
<i>CM</i>	\$ 480.50	✓
<i>Pa</i>	\$ 385.20	X
<i>Pa</i>	\$ 280.50	X
<i>Pa</i>	\$ 195.00	X

less 20%

\$ 5,488.40
\$ 1,097.68
\$ 4,390.72

wiring
spray painting
labour charges
Total

\$ 80.00 *200*
\$ 800.00 *2200*
\$ 800.00 *2000*
\$ 6,070.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

