

HUI YANG MOTOR PTE. LTD.

Kenneth
04/01/2022

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

25/12/2021

Owner: NEU AIK HOU

Not Authorized
61 Pny @ 2250/h
Resurvey After Paint
2 day

ESTIMATE TO REPAIR HONDA VEZEL - SLR8313H

1pc	front LH headlamp	MFCM	\$ 1,759.40	✓
1pc	front LH headlamp lower bracket		\$ 45.00	X
1pc	front bumper 726.60	Bu	\$ 927.50	✓
20pcs	front bumper clip @\$5.00	ru	\$ 100.00	✓
1pc	front bumper grille	pu	\$ 195.20	X
1pc	front bumper lower lid	pu	\$ 485.50	X
1pc	front bumper LH side retainer	DIS	38.10	✓
1pc	front bumper LH fog lamp	pu	\$ 385.50	X
1pc	front bumper LH fog lamp base	su	\$ 85.50	X
1pc	front bumper LH fog lamp garnish	su	\$ 125.50	X
1pc	front centre grille base 351.80	CMS	\$ 480.50	✓
1pc	front centre grille outer garnish	su CMS	\$ 385.20	X
1pc	front wiper tank	pu	\$ 280.50	X
1pc	front LH fender protector	pu	\$ 195.00	X

\$ 5,488.40
\$ 1,097.68
\$ 4,390.72

less 20%

wiring	\$ 80.00	2ol
spray painting	\$ 800.00	22ol
labour charges	\$ 800.00	2ool
Total	<u>\$ 6,070.72</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer
Signature: _____
Date: _____

