



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 39762

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#18-00 / 19-00

THE OCTAGON

S'PORE 069534

ATTN: MOTOR CLAIMS DEPT

DATE : 23/12/2021

CLAIM NO. : 11842

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBL1600A

MAKE/MODEL : HON / CB400SF

*not added
2/5/22
3 days
take photo after repair
27/1/22*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOLT FOOTREST P/N: 47034 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	CU? 10.00
2	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$230.00	CU? 230.00
3	CRASH BAR (ENGINE) P/N: 49567 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$196.00	CU? 196.00
4	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	4.00	\$63.00	220 252.00
5	LEVER BRAKE P/N: 18930 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	502 70.00
6	MIRROR RH P/N: 53470 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$126.00	CU? 126.00
7	MUDGUARD REAR ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$160.00	320 160.00
8	MUFFLER (REAR) YOSHIMURA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$0.00	? 0.00
9	PLATE NUMBER REAR ACRYLIC(YELLOW) P/N: 50935 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	320 20 38.00

*39762 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0383
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$1,082.00
		GST @ 7 %			\$75.74
		GRAND TOTAL (SGD)			<u>\$1,157.74</u>

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*39762 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | **Telephone:** +65 6281 6520 | **Web:** www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0393
ISO 14001:2015