



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21013151/Uvf3n2	
			Date: 14/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMV 1009A	Veh. Inspected	YN 2528L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103631/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	27/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi FK61 (M)	c.c	7545	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	FK61FMA00185	Colour	BLUE	
Odometer	487827 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	8.25 R16	JET WAY	7 mm	
L/H Front Tyre	8.25 R16	JET WAY	7 mm	
R/H Rear Tyre	8.25 R16 (D)	JET WAY	7/7 mm	
L/H Rear Tyre	8.25 R16 (D)	JET WAY	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/12/2021	Inspection Date	30/12/2021	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	