

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

Not Attached
30/12/21
2/5 = 7000
5 days

M/S : SOMPO Insurance Singapore Pte Ltd
 50 Raffles Place #05-01/06 Singapore
 Land Tower Singapore 048623

Estimate No: ES1700941
 Date: 08 Dec 2021
 Policy No: DMCFHQ21-000031
 Veh Reg No: YN2528L
 Make/Model: MITSUBISHI
 FK61FMJ1RDEA
 Chassis No: FK61FMA00185
 Engine No: 6M60154329
 Reg. Date: 28/10/2011

ATTN: Motor Claim Department

Your Ref No: C MM MARKETING M PL
 Claim Type: Third Party
 Accident Date: 08/12/2021
 TP Veh Reg No: SMV1009A

Estimate Repair Cost to Vehicle No :YN2528L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 Front Corner Panel - RH <i>one 891.20</i>	1,465.63	1 PC	1,465.63	✓
2 Front Corner Panel Bracket - RH <i>R</i>	348.34	1 PC	348.34	x
3 Front Bumper <i>Bmf 1391.50</i>	3,106.37	1 PC	3,106.37	✓
4 Front Bumper Bracket - RH <i>Bmf 305.00</i>	389.05	1 PC	389.05	✓
5 Headlamp Assy - RH <i>one 976.58</i>	1,719.61	1 PC	1,719.61	✓
6 Headlamp Rim - RH <i>320 450.00</i>	707.70	1 PC	707.70	✓
7 Headlamp Bracket - RH <i>11</i>	389.05	1 PC	389.05	x
8 Fog Lamp Assy - RH <i>NF</i>	708.44	1 PC	708.44	x
9 Singnal Lamp - RH <i>one 204.60</i>	526.60	1 PC	526.60	✓
10 Front Fender - RH <i>NS</i>	957.59	1 PC	957.59	x
11 Front Fender Seal - RH <i>NS</i>	58.08	1 PC	58.08	x
12 Front Fender Protector - RH <i>NS</i>	81.28	1 PC	81.28	x
13 Step Panel - RH <i>320 805.21</i>	1,025.65	1 PC	1,025.65	✓
14 Step Alloy Mat - RH <i>205.00</i>	453.25	1 PC	453.25	✓
15 Step Panel Protector - RH <i>2.1</i>	245.35	1 PC	245.35	✓
16 Step Panel Side Bracket - RH <i>11</i>	134.86	1 PC	134.86	x
17 Step Panel Bracket - RH <i>11</i>	44.85	1 PC	44.85	x
18 Mudguard Housing - RH <i>2.5</i>	352.69	1 PC	352.69	✓
19 Mudguard Housing Splash Shield - RH <i>Torn</i>	204.28	1 PC	204.28	✓
20 Mudguard - RH <i>2.1</i>	376.29	1 PC	376.29	✓
21 Mudguard Rubber - RH <i>11</i>	81.23	1 PC	81.23	x
22 Front Door Assy - RH <i>2106.27</i>	4,274.85	1 PC	4,274.85	✓
23 Front Door Rubber Seal - RH <i>11</i>	585.74	1 PC	585.74	x
24 Front Door Pillar - RH <i>R</i>	3,165.47	1 PC	3,165.47	x
25 Front Door Hinge Upper - RH <i>See</i>	572.76	1 PC	572.76	x
26 Front Door Hinge Lower - RH <i>See</i>	572.76	1 PC	572.76	x
27 Cabin Rear Panel - RH <i>R</i>	1,664.96	1 PC	1,664.96	x
28 Cabin Rear Inner Panel - RH <i>R</i>	824.53	1 PC	824.53	x
29 Cabin Rear Trim - RH <i>11</i>	2,586.89	1 PC	2,586.89	✓
			27,624.15	
	Less 25%		6,906.04	20,718.15
Labour				
30 Labour to remove & refit front door RH & trasfer parts & realightment .	200.00	1 JOB	200.00	80
31 Labour to remove & refit headlamp ,foglamp ,signal lamp & refocus & checking all wiring .	200.00	1 JOB	200.00	50

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlia@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : SOMPO Insurance Singapore Pte Ltd
 50 Raffles Place #05-01/06 Singapore
 Land Tower Singapore 048623

ATTN: Motor Claim Department

Your Ref No: C MM MARKETING M PL
 Claim Type: Third Party
 Accident Date: 08/12/2021
 TP Veh Reg No: SMV1009A

Estimate No: ES1700941
 Date: 08 Dec 2021
 Policy No: DMCFHQ21-000031
 Veh Reg No: YN2528L
 Make/Model: MITSUBISHI
 FK61FMJ1RDEA
 Chassis No: FK61FMA00185
 Engine No: 6M60154329
 Reg. Date: 28/10/2011

Estimate Repair Cost to Vehicle No : YN2528L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
32 Labour change to remove & refit & dismantle & weld & cut & renew all above parts .	2,500.00	1 JOB	2,500.00	1200
33 To spray & painting at accident dented area .	1,600.00	1 JOB	1,600.00	900
34 To rust proofing on affected area .	890.00	1 JOB	890.00	60
			5,390.00	5,390.00
			Total	S\$ 26,108.15
			Add GST @ 7%	1,897.57
			Total Amount Payable	<u>S\$ 28,005.72</u>

TOTAL: SINGAPORE DOLLAR TWENTY EIGHT THOUSAND AND FIVE AND CENTS SEVENTY TWO ONLY

**For MAH LIAN MOTOR VEHICLE
REPAIRER**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7-8673-98