

Automobile Hub SLNS429Z. 2017 May.

1P Chim. Honda Vezel Hybrid 1496cc

Veron. RU31236738.

Rear Number Plate.	Best	30(SN) /
Rear Number Plate Holder	Dehnd	30(SN) /
Rear Number Plate Lamp x02	MP New	38.5 x 2 = 77. x
Rear Bumper	Distorted	762.70 /
Rear Bumper Clips.	MP	30(SN) /
Rear Bumper Side Holder x02	MP	23.5 x 2 = 47. /
Rear Bumper Lower Garnish.	Dehnd	500(SN) 680(SN) /
Rear Bumper Reflector x02	LH angled RH wt	141.1 x 2 = 282.20 /
Reverse Sensor.	Damaged	280(SN) . 200(SN)
Rear End Panel	Distorted	585 /
Rear End Panel Top Garnish	Dehnd	98.40 /
Rear End Panel Top Garnish Clips.	MP	20(SN) /
Rear End Panel Sealant.	New	60(SN) /

SLN 5429Z.

Rear End Panel Buzzes cracked 85-²⁰00 ✓

Rear End Panel Antenna Sensor cracked 60-10 ✓

Tailcap x02 ^{wt} 474.6 x 2 = 949.20 ✓

Tailcap Inner Apron x02 Deformed 195 x 2 = 390 ✓

Tailgate Distorted 1100 ✓

Tailgate Lock Jammed 182-50 ✓

Tailgate Lock Striker ^{NE NE} 24-70 +

Tailgate Weatherstripe ^{wt} 165-40 ✓

Tailgate Dumper x02 ^{NE NE} 182.7 x 2 = 365.40 +

Tailgate Reflector x02 cracked 413.2 x 2 = 826.40 ✓

Tailgate Pull Pocket Deformed 27-50 ✓

Tailgate Outer Handle Switch ^{NE} 125.50 +

Tailgate Outer Garish. cracked 325 ✓

Tailgate Inner Trim Board Deformed 285.60 ✓

Tailgate Inner Trim Board Clips. ^{NE} 30 (SN) ✓

Tailgate Glass Moulding ^{NE} 120 ✓

SLNSH29Z

Tailgate Glass Sealant. New 60(SN) ✓

Rear Fender Inner Trim Board x 02 Deformed 305.2 x 2 = 610.40 ✓

Rear Fender Inner Trim Board Clips. New 60(SN) ✓

Rear Fender Inner Shield x 02 } 147.5 x 2 = 295⁺

Rear Fender Inner Shield Clips. } NH
New 60(SN) x
196

Rear Fender Wheel Arc Garnish x 02 LH Deformed 196 x 2 = 392

Rear Fender Wheel Arc Garnish Clips. New 40(SN) ✓
20(SN)

Spare Tyre Panel. Buckled 1130 ✓

Spare Tyre Panel Undercover Deformed 225.10 ✓

Spare Tyre Panel Undercover Clips. New 30(SN) ✓

Spare Tyre Panel Top Cover Deformed 306.60 ✓

Spare Tyre Panel Top Rubberised Mat NH
New 280(SN) x

Tools Tray. Deformed 310.90 ✓

Hybrid Battery Air Duct. NH
New 110.20 x

SLN 5429Z

Hybrid Battery Top Metal Cover	} NP MC	325.70	X
Hybrid Battery Lower Tray		346.	X
Rear Exhaust Pipe	Best	598.60	✓
Rear Exhaust Mounting	new	28.50	+
Rear Exhaust Heat Shield	implied	98.30	✓
Rear Exhaust Pipe	not new	762.90	+
Rear Camera	NP new	780(SN)	X
Front Number Plate	Best	30(SN)	✓
Front Number Plate Holder	Deband	30(SN)	✓
Front Bumper	Deband	801.70	✓
Front Bumper Clips	new	30(SN)	✓
Front Bumper Side Holder x02	new	25.1x2=50.20	✓
Front Bumper Lower Grille	Deband	77.50	✓
Front Bumper Tow Covers	NP new	20.20	X

SLN5429Z.

Front Bumper Lower Spoiler	Dented	70(SN) 580(SN)
Front Bumper Fog Lamp x02	NY	$327.7 \times 2 = 655.40$ X
Front Bumper Fog Lamp Cover x02	re	$78 \times 2 = 156$ X
Front Bumper Reinforcement.	Dented	321 ✓
Front Bumper Reinforcement Top Mending x02	re	$35 \times 2 = 70$ X
Front Grille	Cracked	421.60 ✓
Front Grille Base	Cracked	351.80 ✓
Front Grille Clips	re	30(SN) ✓
Front Grille Chrome Molding	Cracked	283.90 ✓
Front Grille Lower Bracket	Cracked	76.20 ✓
Florida Logo.	re ✓	3490 ✓
Headlamp x02	Cracked	$1784.5 \times 2 = 3569$ ✓
Headlamp Lower Bracket x02.	Cracked	$39 \times 2 = 78$ ✓
Bonnet	Dented	892.30 ✓
Bonnet hook	re re	95.10 X
Bonnet Weatherstripe	NY re	75 X

SLN 5429Z.

Front Support Panel Repairs	676.40	x
Front Support Panel Top Cover Rebound	190.30	/
Front Support Panel Top Cover Clips. ^{new} 20(SN).		/
Air Con Condenser Dented	898.	✓
Air Con Condenser Side Guide x 02	36 x 2 = 72	+
Air Con Condenser Side Guide Clips. ^{new} 20(SN).		x.
Radiator ^{Not new}	1250.60	+
Radiator Coolant. ^{new}	50(SN).	x
Front Fender x 02 ^{new}	382 x 2 = 1164.	+
Front Fender Wheel Arc Garnish x 02 ^{new}	153 x 2 = 306.	+
Front Fender Wheel Arc Garnish Clips ^{new}	40(SN).	+

4687.30

17814.50. S.N: 1790

14251.60

SLN 5429Z

Panel Bending (Rear)	1800 1200
Spray Painting (Rear)	1600 1000
Wiring (Rear),	50 30
To spray dust coat (Rear)	150 100
To remove reverse sensor (Rear)	120 50
To remove rear camera (Rear)	120 50
To remove upholstery and rear seat (Rear).	300 200
To remove tailgate glass (Rear)	180 120
To transfer tailgate fittings (Rear).	150 80
To remove rear and centre exhaust pipes (Rear)	300 80
To remove hybrid battery (Rear).	450 380

5180

SLN54292

Panel Beating (Front)

~~1000~~ 500

Spray Painting (Front)

~~800~~ 500

Wiring (Front)

~~50~~ 30

To remove condensers
and to top up air con gas (Front) }

~~120~~ 60

To remove radiator and
to top up coolant (Front) }

120. X

2090

35,402.10

A380

Total: 20421.60

L/S: 16.3K.

14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: