

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21013156/T1vy3e2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 04/01/2022 SINGAPORE 068811 ATTN: PAY DANIEL Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHA 1406G **SLE 7348H** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03PE5 Excess (\$) 0.00 **PAY DANIEL Assign Date** 27/12/2021 Assign From **Vehicle Particulars & Condition** 2. MAZDA ROADSTER S 1496 Make & Model C.C SPECIAL Engine No. **HIDDEN** Year of Reg. 2016 Chassis No. ND5RC108997 Colour **GREY** 41038 KM **IN ORDER** Odometer Steering **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Make **Balance** 205/45 R17 GOODYEAR 6 mm R/H Front Tyre 205/45 R17 GOODYEAR L/H Front Tyre 6 mm R/H Rear Tyre 205/45 R17 **GOODYEAR** 6 mm 205/45 R17 GOODYEAR L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. **General Information** 5. **Accident Date** 23/12/2021 **Inspect Date / Time** 28/12/2021 (03:20 PM) 1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit Survey held at TSA TRANSPORT Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM21013156/T1vy3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

 ${\tt BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE}$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.