

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21013157/DGA3Q2**Date:** 25/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0006372\_01

**Claimant Vehicle No :** GBF4603D **Insured Vehicle No :** SHD2297G

Date of Loss: 22/12/2021 Nature of Claim: TP Claim No: MFL2021D0005643

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4603D**

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR EURO V (M) Engine No: YD25406579A

Reg. Date: 05/11/2016 (Man. Year: 2016) Chassis No: JN1MC2E26Z0007244

Colour: White Odometer: 43896 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Dunlop 5 mm Rear Left Side: Falken 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	400.00	400.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>800.00</b>	<b>400.00</b>	<b>400.00</b>	<b>50.00</b>
<b>+ Loss of Use (2.0 x S\$25.00/day) (S\$)</b>		50.00		
		<b>(S\$)</b>		
		450.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>225.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>232.45</b>		

INSPECTION

Date of Assignment: 27/12/2021

Date Inspected: 29/12/2021 Inspected At:

Estimated Period of Repair: 2.0 days

Sg 98 Motor Pte Ltd (HQ)  
BLK 4001 ANG MO KIO INDUSTRIAL PARK 1  
#01-21  
Singapore 569622

**Adjuster:** BRYAN TANI**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Jun 2022)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR EURO V (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4603D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR KNOCKING AND REPAIR FRONT BUMPER AND FRONT LEFT DOOR	New	400.00	200.00
2	SPRAY PAINTING FRONT BUMPER AND FRONT LEFT DOOR	New	400.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>800.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >