



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21013164/Gtf3e2 Date: 07/04/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1581T	Veh. Inspected	SLD 3383L
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/12/21/5039	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	27/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ A180	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDD1760422J460872	Colour	BLACK
	Odometer	53847 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45Z R17	TOYO	6 mm
	L/H Front Tyre	225/45Z R17	TOYO	6 mm
	R/H Rear Tyre	225/45Z R17	TOYO	6 mm
	L/H Rear Tyre	225/45Z R17	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/12/2021	Inspection Date	30/12/2021
	Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	