

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2112/017
Policy No:	QAM21A00001100	Date of Loss:	20/12/2021
Vehicle Reg. No.:	SLD3383L	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SMB1581T
Any Injuries?	no	Contact No:	
Insured/Claimant:	KAILI XUAN TRADING	Driver:	CHUA LONG KAI

PARTS MODEL

Make/Model:	Mercedes-Benz, A180(R17)	Vehicle Reg. Date:	
	- WDD176	Engine Number:	-
Vehicle Colour:	-	Odometer:	-
Chassis No:	-	Est. Duration of Repair(Day)	5
Total Loss?	-		

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO GIA REPORT
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	894.32
Miscellaneous Items	0.00
Labour	650.00
Paintwork Labour	850.00
Towing	0.00
Gross Total(\$\$):	2,394.32
GST 7.00%(\$\$):	167.60
Nett Amount(\$\$):	2,561.92

This claim is handled by: Tee Shu yi

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT DOOR SIDE MIRROR RH <i>cut</i>	534.60	-20.00	427.68
2	1	FRONT DOOR SIDE MIRROR COVER RH <i>cut</i>	243.10	-20.00	194.48
3	1	FRONT DOOR SIDE MIRROR GLASS RH <i>cut</i>	129.00 486.7	-20.00	103.68 389.36
4	1	FRONT DOOR OUTER MOULDING RH <i>cut</i>	210.60	-20.00	168.48
5	1	FRONT FENDER RH <i>x</i>	0.00	0.00	0.00
6	1	FRONT BONNET <i>x</i> <i>repair</i>	0.00	0.00	0.00
Total Parts (\$)					894.32 1180

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
Sub Total (\$)					0.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	650.00	0.00	650.00
Gross Labour Cost (\$)					650.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	850.00	0.00	850.00
Gross Labour Cost (\$)					850.00

< END OF ESTIMATES > 2080

*3 Days.
Paint by part.
After repair photos.
Gmo Qiang - 82880282.
30/12/21.*

LIX Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: