

ASS. REG. BY:

REF:

A/G/ 21013166/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUB 5861X

Yr Regn:

04, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour

In Black

A/C:

Insured / Std / NI / NA

Sp. Reading

102456

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1109268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/12/21

D.O.I.

28/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/13 21:00 & 22501 Custom

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : FRANSISKUS ERICK SAPUTRO
23 TERRASSE LANE #05-21

SINGAPORE 544775

ATTN:

Your Ref No: SLB5861X

Claim Type: Third Party → MG

Accident Date: 22/12/2021

TP Veh Reg No: SBJ4000Y

Estimate No: MC1902368

Date: 23 Dec 2021

Policy No: MT/00363257/04

Veh Reg No: SLB5861X

Make/Model: HONDA VEZEL 1.5X
CVT

*Not Authorize
11 Rm @ 2250/-
Recovery After Paint*

4 days

Estimate Repair Cost to Vehicle No :SLB5861X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR WINDSCREEN MOULDING TOP	1 PC	42.10	✓
2 REAR WINDSCREEN MOULDING LH & RH	2 PC	62.40	✓
3 REAR WINDSCREEN MOULDING BTM	1 PC	28.40	✓
4 TAILGATE	1 PC	901.70	✓
5 TAILGATE EMBLEM	1 PC	30.10	X
6 TAILGATE VEZEL LOGO	1 PC	43.10	✓
7 TAILGATE LAMP RH	1 PC	38.50	X
8 TAILGATE STOPPER RH	1 PC	15.10	X
9 TAILGATE LOCK	1 PC	130.10	X
10 TAILGATE RUBBER	1 PC	101.30	X
11 TAILGATE INNER TRIMBOARD BTM	1 PC	153.40	✓
12 TAILAMP RH	1 PC	503.10	X
13 REAR BUMPER	1 PC	553.10	✓
14 REAR BUMPER REFLECTOR RH	1 PC	50.10	X
15 REAR BUMPER CORNER RH	1 PC	195.10	✓
16 REAR BUMPER SIDE RETAINER RH	1 PC	17.50	X
17 REAR BUMPER CLIPS	12 PC	70.68	✓
18 REAR FENDER WHEEL ARCH RH	1 PC	172.10	✓
19 REAR FENDER COWLING RH	1 PC	133.40	X
20 REAR FENDER COWLING CLIPS	8 PC	47.12	X
		3,288.40	
	Less 20%	657.68	2,630.72
Special Nett			
21 REVERSE SENSOR	1 SET	200.00	✓
22 INNER SEAL	1 PC	20.00	✓
23 WINDSCREEN SEALANT	1 PC	40.00	✓
		260.00	260.00
LABOUR			
24 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/-
25 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
26 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	50/-
27 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/-

Zila
Ah Lim Motor Company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : FRANSISKUS ERICK SAPUTRO
23 TERRASSE LANE #05-21

SINGAPORE 544775

ATTN:

Your Ref No: SLB5861X
Claim Type: Third Party
Accident Date: 22/12/2021
TP Veh Reg No: SBJ4000Y

Estimate No: MC1902368
Date: 23 Dec 2021
Policy No: MT/00363257/04
Veh Reg No: SLB5861X
Make/Model: HONDA VEZEL 1.5X
CVT

Estimate Repair Cost to Vehicle No :SLB5861X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
28 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER RH,REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	400
29 TO SPRAY TAILGATE,REAR BUMPER,REAR FENDER LH,REAR END PANEL.	1 PC	900.00	320
		1,980.00	1,980.00
		Total	S\$ 4,870.72
		Add GST @ 7%	340.95
		Total Amount Payable	S\$ 5,211.67

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED ELEVEN AND CENTS SIXTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

Ah Lim Company
AUTHORISED SIGNATURE