

Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00
Re-set Rear ABS System	1	\$400.00	\$400.00
Remove/Refix Fuel Tank	1	\$80.00	\$80.00
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00
Re-set Rear Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor	1	\$550.00	\$550.00
TOTAL LABOUR			\$6,850.00
ESTIMATE TOTAL			\$ 33,185.10

150/-
 44
 44
 60/-
 44
 44
 60/-
 } 150/-
 2890.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

27/12/2021 @ 12:00pm
 N/A Andrew
 3/Part 8 days.
 nyan

~~P/P 17,822.20~~
 P/P 17,802.20 =

LKK Aud




Photo of
 repair
 with damaged
 parts.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: