

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WINNIE MAK SERVICES
BLK 574 HOUGANG ST 51 #04-01
SINGAPORE 530574

Contact : 96732483

TP A x A.
Ashes.

TAX INVOICE

Repair Code : CLM15396

Date in : 23/12/2021

Vehicle Num. : GBK3611K

Model : NISSAN NV200 1.6 (A) PETROL

Chassis/Eng# : JN1YAAM20Z0000522/HR16158295D

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>reborn d</i>	1	541.50	✓ 541.50
FRONT BUMPER REINFORCEMENT <i>xben</i>	1	625.90	✗ 625.90
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	25.00	✓ 50.00
FRONT BUMPER SPONGE <i>could</i>	1	326.50	118 ✓ 326.50
FRONT BUMPER TOW HOOK COVER <i>ut</i>	1	21.00	✓ 21.00
FRONT GRILLE <i>could</i>	1	356.20	✓ 356.20
FRONT GRILLE 'LOGO' EMBLEM <i>ru</i>	1	64.90	✓ 64.90
FRONT HEADLAMP L/R <i>2H could</i>	2	489.90	489.90 979.80
FRONT HEADLAMP LOWER GARNISH L/R <i>PRH Del d</i>	2	320.00	320 640.00
Subtotal before discount			3,605.80
Percentage discount 10%			360.58
Sub-total 1			3,245.22
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00
FRONT BUMPER NUMBER PLATE <i>30nd</i>	1	25.00	✓ 25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	50.00	30 50.00
Subtotal before discount			155.00
Percentage discount 0%			0.00
Sub-total 2			155.00
Parts-total			3,400.22

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

WINNIE MAK SERVICES
BLK 574 HOUGANG ST 51 #04-01
SINGAPORE 530574

Contact : 96732483

TAX INVOICE

Repair Code : CLM15396

Date in : 23/12/2021

Vehicle Num. : GBK3611K

Model : NISSAN NV200 1.6 (A) PETROL

Chassis/Eng# : JN1YAAM20Z0000522/HR16158295D

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

30 80.00

200 500.00

300 600.00

X 80.00

1,260.00

4,660.22

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Abian Lj

28/12/21

H/S 03 Days

total. 238035

H/S: 1-91K