

REPAIR ESTIMATE

DATE: 27-Dec-21INSURANCE: AIG ASIAMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHB6353L

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$430.90 <i>ky</i>
	Front Bumper Side Bracket RH	1		\$35.00 <i>X nn</i>
	Front Bumper Clips	10	\$2.20	\$22.00 <i>X nn</i>
	Front Fender RH	1		\$588.80 <i>ht</i>
	Front Fender Shield RH	1		\$164.70 <i>X nn</i>
	Front Fender Blue-Drive RH	1		\$26.60 <i>ne</i>
	Front Wheel Cap RH	1		\$346.40 <i>ant</i>
	Front Bumper Grille RH	1		\$93.45 <i>X nn</i>
	Headlamp RH	1		\$1,993.65 <i>X nn</i>
	SUB TOTAL		<i>983.80</i>	\$3,701.50
	LESS 20%			\$740.30
	DISCOUNTED TOTAL		<i>787.04</i>	\$2,961.20
	Frt Fender Adv.Sticker RH	1		\$100.00 <i>nd</i>
	Frt Door Adv.Sticker RH	1		\$100.00 <i>nd</i>
	Front Door ComfortDelGro RH	1		\$75.00 <i>nd</i>
	NETT TOTAL		<i>275</i>	\$275.00
	TOTAL SPARE PARTS			\$3,236.20
	Labour Charge			
	Panel Beating			\$800.00 <i>525-</i>
	Spray Painting			\$900.00 <i>750-</i>
	Check Wirings			\$40.00 <i>X nn</i>
	Tuff Kote		<i>1385</i>	\$40.00 <i>30-</i>
	Wheel Alignment			\$120.00 <i>80-</i>
	TOTAL LABOUR		<i>\$2447.04</i>	\$1,900.00
	ESTIMATE TOTAL		<i>03 days</i>	\$5,136.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by the Surveyor appointed by the insurance company.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tamphi 92495787
wp' 27/12/21 C Spm
p/p resurvey before part
03 days
Tamphi@khanh.com