

Lapac Ins. Bhd.
300 Beach Rd
#17-04/07 The Concourse
Singapore 199555

Date: 23/12/21

Attn.: Motor Claims Department

Dear Sir/Madam

RE: Accident involving vehicles SFU 6257 E & SJY 8346A

On 18/12/21 at BK 156 Taglinen St 12.

It is in my opinion that the above mentioned accident was caused solely by the negligence of the driver of the vehicle no: SJY 8346A

As the above vehicle was insured by your insurance company at the material time of the accident. I would appreciate that you could kindly arrange your surveyor to survey my vehicle soonest possible at the following address :-

Kan Fook Sing Motor Workshop
61 Defu Lane 12
Singapore 539147
Tel : 67479560 (O)

Thank you

Yours faithfully





簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 22-12-2021

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

VEHICLE NO. : SFU6257E

ACCIDENT DATE : 18-12-2021 14:35

THIRD PARTY REF. : SJY8346A

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SFU6257E RENAULT MEGANE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT GRILLE	600.00
2	1	FRONT BUMPER	750.00
3	1	FRONT BUMPER REINFORCEMENT	380.00
4	1	FRONT BUMPER LOWER GRILLE	250.00
5	10	FRONT BUMPER CLIP@\$4.50	45.00
			<hr/>
			2,025.00
			<hr/>
			ADD 20 %
			405.00
			<hr/>
			TOTAL (A)
			2,430.00
			<hr/>
			SPECIAL NETT ITEMS
1	1	FRONT NUMBER PLATE	30.00
			<hr/>
			TOTAL (C)
			30.00
			<hr/>
			LABOUR CHARGES
1	1	TO CHECK WIRING SYSTEM	30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	550.00
3	1	SPRAYPAINTING CHARGES	400.00
			<hr/>
			TOTAL (D)
			980.00
			<hr/>
			ESTIMATE TOTAL
			3,440.00
			<hr/>