

(08/11/13) Wef

ASS. REC. BY: Rana

REF:

CC4/ARB21013186/Ries3

683H

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLO 2511R

at Workshop m/s

CHARN CUSTOM CRAFTof 1010 BUKIT MERAH LN 3 # 01-105

Insured:

GRB

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

53k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLO 2511RYr Regn: 2016 / JunType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda SHUTLE 1.5G CVTc.c 1496

Colour:

BLACKA/C: Insured / Std / NI / NA

Sp. Reading:

082887T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

6K81002532Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/12/21

D.O.I.

30/12/21

Survey held at

CHARN'S CUSTOM CRAFTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 23K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

): S + RS / SI☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐


: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

NTUC/III(SLR4718A)

DOA: 24/12/2021@1020HRS

INDIA INTERNATIONAL INSURANCE PTE LTD

27/12/2021

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLD 2511 R - HONDA SHUTTLE 1.5G CVT

CHASSIS NO: GK81002532 (2016)

1 pc	Rear windscreen moulding <i>ne ✓</i>	\$ 138.50
1 pc	Rear boot <i>bt ✓</i>	\$ 995.00
1 pc	Rear boot emblem 'SHUTTLE' <i>ne ✓</i>	\$ 55.00
1 pc	Rear boot emblem logo <i>ne ✓</i>	\$ 55.00
1 pc	Rear boot lock <i>? bt ✓</i>	\$ 131.80
1 pc	Rear boot rubber <i>ne ✓</i>	\$ 138.50
1 pc	Rear bumper <i>de ✓</i>	\$ 1,209.00
1 pc	Rear end panel <i>bt - photo? ✓</i>	\$ 465.00
1 pc	Rear end panel top garnish <i>de ✓</i>	\$ 155.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LESS 20%

\$ 3,343.40
\$ 668.68
2674.72

2674.72 \$ 2,674.72

1 pc	Rear windscreen sealant (S/NETT) <i>ne ✓</i>	\$ 35.00
1 set	Reverse Sensor (S/NETT) <i>? nw ✓</i>	\$ 200.00

Remove and reinstall rear windscreen

Check wiring function

Apply rust-proofing on affected areas.

Remove necessary parts: jacking, panel beating, repair and
straighten rear inner panel, spare tyre compartment inclusive
replacing the above.

235.00 \$ 35.00
1410.00 \$ 200.00
4319.72 \$ 120.00
269 \$ 40.00
3455.77 \$ 80.00
45-\$3,450 \$ 800.00
235
2410

Putty and respray rear inner panel, rear end panel, rear boot,
rear bumper and spare tyre compartment.

ADD 7% GST

Rasul \$ 800.00
\$ 4,749.72
Hp 90010068 \$ 332.48
\$ 5,082.20

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

6 days
4/8
30/12/21 @ 1110

Resin after repair

CHARN'S CUSTOMCRAFT