



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg

Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

NTUC/III(SLR4718A)

DOA: 24/12/2021@1020HRS

INDIA INTERNATIONAL INSURANCE PTE LTD

27/12/2021

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLD 2511 R - HONDA SHUTTLE 1.5G CVT

CHASSIS NO: GK81002532 (2016)

1 pc	Rear windscreen moulding	\$ 138.50
1 pc	Rear boot	\$ 995.00
1 pc	Rear boot emblem 'SHUTTLE'	\$ 55.00
1 pc	Rear boot emblem logo	\$ 55.00
1 pc	Rear boot lock	\$ 131.80
1 pc	Rear boot rubber	\$ 138.50
1 pc	Rear bumper	\$ 1,209.00
1 pc	Rear end panel	\$ 465.00
1 pc	Rear end panel top garnish	\$ 155.60
		<hr/>
		\$ 3,343.40
	LESS 20%	\$ 668.68
		<hr/>
		\$ 2,674.72
1 pc	Rear windscreen sealant (S/NETT)	\$ 35.00
1 set	Reverse Sensor (S/NETT)	\$ 200.00
	Remove and reinstall rear windscreen	\$ 120.00
	Check wiring function	\$ 40.00
	Apply rust-proofing on affected areas.	\$ 80.00
	Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, spare tyre compartment inclusive replacing the above.	\$ 800.00
	Putty and respray rear inner panel, rear end panel, rear boot, rear bumper and spare tyre compartment.	\$ 800.00
		<hr/>
		\$ 4,749.72
	ADD 7% GST	\$ 332.48
		<hr/>
		\$ 5,082.20

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....