

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

FOOK KEE TRADING SERVICE PTE LTD
 35 TANNERY ROAD #09-06 RUBY
 INDUSTRIAL COMPLEX
 SINGAPORE 347740

TP AXA-
 Asher.

TAX INVOICE

Repair Code : CLM17040

Date in : 22/12/2021

Vehicle Num. : GBK5520B

Model : TOYOTA HIACE VAN TURBO 5DR MT

Chassis/Eng# : JTFHT02P200250660/1KDB046670

Contact : 90038002, 87232892

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Defend</i>	1	541.20	✓ 541.20
FRONT BUMPER LH FOGLAMP GARNISH <i>could</i>	1	56.40	✓ 56.40
FRONT BUMPER LOWER GRILLE <i>could</i>	1	178.10	✓ 178.10
FRONT BUMPER SIDE RETAINER L/R <i>2H Defend</i>	2	244.90	120 ✓ 489.80
FRONT GRILLE <i>new</i>	1	1173.50	+ 1,173.50
FRONT LH DOOR <i>Dented</i>	1	1887.10	1745 ✓ 1,887.10
FRONT LH DOOR HINGE (LOWER) <i>2</i>	1	110.00	+ 110.00
FRONT LH DOOR HINGE (TOP) <i>new</i>	1	110.00	+ 110.00
FRONT LH DOOR WEATHER STRIP <i>3006.75</i>	1	230.10	+ 230.10
FRONT LH DOOR WIRE HARNESS COVER <i>could</i>	1	93.40	✓ 93.40
FRONT LH HEADLAMP <i>cut</i>	1	744.00	✓ 744.00
FRONT LH STEP GARNISH <i>Defend</i>	1	161.90	✓ 161.90
FRONT LH STEP PANEL <i>Dented</i>	1	369.00	✓ 369.00
Subtotal before discount			6,144.50
Percentage discount 25%			1,536.13
Sub-total 1			4,608.38
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	30 ✓ 80.00
FRONT GRILLE CLLIPS - SET <i>new</i>	1	40.00	+ ✓ 40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

FOOK KEE TRADING SERVICE PTE LTD
 35 TANNERY ROAD #09-06 RUBY
 INDUSTRIAL COMPLEX
 SINGAPORE 347740

TAX INVOICE

Repair Code : CLM17040
 Date in : 22/12/2021
 Vehicle Num. : GBK5520B
 Model : TOYOTA HIACE VAN TURBO 5DR MT
 Chassis/Eng# : JTFHT02P200250660/1KDB046670

Contact : 90038002, 87232892

FRONT LH DOOR COMPANT STICKER	<i>NEC</i>	1	25.00	<i>✓</i>	25.00
FRONT LH HEADLAMP CLIPS - SET	<i>nm</i>	1	25.00	<i>10</i>	25.00
FRONT LH STEP GARNISH CLIPS - SET	<i>nm</i>	1	30.00	<i>20</i>	30.00
Subtotal before discount					200.00
Percentage discount 0%					0.00
Sub-total 2					200.00
Parts-total					4,808.38

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total 2,120.00
Parts & Labour Total 6,928.38

1270
~~30~~ 60.00
~~80~~ 80.00
~~800~~ 1,000.00
~~50~~ 900.00
~~60~~ 80.00

*Admin Lj
 r/s 07/01/22*

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature

050 days

Total: 9361.75

w/s: 3.4K ✓