

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9696S***NOT Withheld  
Reserve B4 pgm***AAD2112-140***86413-90*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**28 DEC 2021****SHD9696S**

JTDKB3FU503082627

TOYOTA

PRIUS

27/12/2021

**LONPAC**

01/08/2019

<b>PART</b>		<b>LIST</b>	
1	COVER, REAR BUMPER	\$	<i>HL</i> 442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>B1</i> 332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>HL</i> 15.40 ✓
1	GUARD, REAR BUMPER, CENTER	\$	<i>B1</i> 576.30 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>SL</i> 116.50 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>SL</i> 117.70 X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>B1</i> 1,147.80 ✓
1	SPOILER SUB-ASSY, REAR	\$	<i>CMT</i> 1,575.40 ✓
1	LAMP SET, STOP CENTER	\$	<i>CM</i> 192.30 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>HL</i> 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>HL</i> 54.60 ✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>HL</i> 47.90 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>CMT</i> 925.60 ✓
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i> 259.20 X
1	WEATHERSTRIP, BACK DOOR	\$	<i>SL</i> 372.30 X
1	COVER, FLOOR UNDER, NO.1 LH	\$	<i>SL</i> 175.10 X
1	COVER, FLOOR UNDER, NO.2 RH	\$	<i>SL</i> 241.90 X
1	COVER, REAR FLOOR CTR	\$	<i>SL</i> 229.90 X
1	COVER, DECK TRIM, REAR	\$	<i>SL</i> 126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>HL</i> 650.30 X
1	STAY ASSY, BACK DOOR, LH	\$	<i>SL</i> 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	<i>SL</i> 242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>HL</i> 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>HL</i> 61.00 X
<b>TOTAL</b>		<b>\$</b>	<b>8,261.80</b>
<b>25%</b>		<b>\$</b>	<b>2,065.45</b>
		<b>\$</b>	<b>6,196.35</b>



**Trans-cab Auto Services Pte Ltd****AAD2112-140**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9696S****Special Nett**

1SET PARKING AID	\$	<i>DA</i> 700.00 <i>220SA</i>
1SET REAR BUMPER CLIP	\$	<i>NA</i> 95.00 <i>50SA</i>
2 WINDSCREEN SEALANT	\$	<i>NA</i> 150.00 <i>80SA</i>
1 WINDSCREEN MOULDING	\$	<i>NA</i> 200.00 <i>—</i>
1 WINDSCREEN INNER SPONGE SEAL	\$	<i>NA</i> 130.00 <i>30SA</i>
1 REAR BUMPER PROTECTOR	\$	<i>NIP</i> 180.00 <i>X</i>
1SET REAR BUMPER RETAINER CLIP	\$	<i>NA</i> 85.00 <i>X</i>
1 REAR SPOILER CLIP	\$	<i>NA</i> 70.00 <i>X</i>
1 END PANEL TRIM CLIP	\$	<i>NA</i> 65.00 <i>X</i>
1 REAR TAILGATE STICKER "Trans-Cab"	\$	<i>NA</i> 80.00 <i>30SN</i>
1 REAR TAILGATE STICKER "6555-3333"	\$	<i>NA</i> 80.00 <i>30SN</i>
1 REAR NUMBER PLATE WITH MOULDING	\$	<i>NA</i> 200.00 <i>X</i>
<b>TOTAL</b>	<b>\$</b>	<b>2,035.00</b>

**TOTAL PARTS \$ 8,231.35****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00 <i>1801</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 <i>5001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>NA</i> 380.00 <i>X</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00 <i>601</i>
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>NA</i> 480.00 <i>X</i>

**Trans-cab Auto Services Pte Ltd****AAD2112-140**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9696S**

To transfer of Fender fittings, attachments and perform water seepage test.	\$	na	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	4	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na	250.00	X
Towing Fees	\$	na	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	8801
To reinstall rear bumper parking sensor.	\$		170.00	501
To Check Electrical Lighting Concerned.	\$		170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na	220.00	X
To replace, refix and top up coolant for radiator	\$	4	170.00	X
To lift-up / out engine with gear box and refit.	\$	4	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	4	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	4	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>10,290.00</b>	



**Trans-cab Auto Services Pte Ltd**

**AAD2112-140**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD9696S**

Over All Total	\$	<b>18,521.35</b>
----------------	----	------------------

**(PART-BY-PART) Repair Days**

~~25 DAYS~~

*3 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: