

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD95K

Not Authored
61 Sep 8/550h

AAD2112-

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

28 DEC 2021

SHD95K
 VF1ABL15AUC282163
 RENAULT
 LATITUDE
 26/12/2021
 III
 14/08/2015

PART	LIST
1 FENDER PANEL REAR RH	\$ 1,933.20 X
1 DOOR PANEL FRT RH <i>1454.00</i>	\$ 2,844.66 ✓
1 DOOR WEATHERSTRIP FRT RH	\$ 410.27 X
1 DOOR HANDLE OUTER FRT RH	\$ 477.76 X
1 DOOR HANDLE MODULE FRT RH	\$ 133.60 X
1 DOOR REGULATOR FRT RH	\$ 505.19 ✓
1 DOOR REGULATOR MOTOR FRT RH	\$ 796.46 ✓
1 DOOR HINGE UPPER FRT RH	\$ 261.28 X
1 DOOR HINGE LOWER FRT RH	\$ 300.55 X
1 DOOR PANEL REAR RH	\$ 2,844.66 ✓
1 DOOR WEATHERSTRIP REAR RH	\$ 311.60 X
1 DOOR HANDLE MODULE REAR RH	\$ 133.40 X
1 DOOR HANDLE OUTER REAR RH	\$ 42.10 X
1 DOOR REGULATOR REAR RH	\$ 450.60 X
1 DOOR REGULATOR MOTOR REAR RH	\$ 758.10 X
1 DOOR HINGE UPPER REAR RH	\$ 241.60 X
1 DOOR HINGE LOWER REAR RH	\$ 169.90 X
1 ROCKER PANEL OUTER RH	\$ 1,184.99 ✓
	\$ 13,799.92
	10% \$ 1,379.99
	\$ 12,419.93

Special Nett	
1 FENDER CLIP	\$ 60.00 X
1 DOOR TRIM CLIP	\$ 70.00 X
1 DOOR SEAL CLIP	\$ 65.00 X
1 DOOR MOULDING CLIP	\$ 70.00 X
1 DOOR STICKER TRANSCAB	\$ 100.00 <i>60.00</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHD95K

- 1 DOOR STICKER 65553333
- 1 DOOR STICKER CLASSIC
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

Car All Total	\$	nn	100.00	6000
	\$	nn	100.00	3000
(LUMP SUM)	\$	nn	150.00	X
Repair Days	\$	nn	200.00	X
	\$	nn	130.00	X
TOTAL	\$		1,045.00	
TOTAL PARTS	\$		13,464.93	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	1100
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	700
To Rust-Proofing Of The Affected Areas.	\$		170.00	90
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Check Electrical Lighting Concerned.	\$		170.00	20
TOTAL	\$		10,240.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD95K

AAD2112-

SINGAPORE ACCIDENT STATEMENT

Over All Total \$ 36,124.85

(LUMP SUM)

Repair Days ~~20 DAYS~~

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Insured

Model

Year

Check whether the vehicle was being used at time of accident

Are you presently under your own insurance policy for repair to your vehicle?

Yes/No

Signature

Date

Signature of Repairer

Name of Insurance Company

Type of Coverage

Third Party

Third Party

Signature of Insured

Date

Repairer

LATITUDE 100-001 AUTO (P) LTD

Private Hire

No - Claiming Third Party

Yes

Amount

1998

ATA Insurance Ltd Ltd

Third Party

Yes

Signature

Signature of Insured

Date