

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD95K*Not Available*
*U/Sup 8/55ch***AAD2112-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

28 DEC 2021**SHD95K**

VF1ABL15AUC282163

RENAULT

LATITUDE

26/12/2021

III

14/08/2015

PART		LIST	
1	FENDER PANEL REAR RH	\$	<i>R</i> 1,933.20 X
1	DOOR PANEL FRT RH <i>1454.00</i>	\$	<i>B</i> 2,844.66 ✓
1	DOOR WEATHERSTRIP FRT RH	\$	<i>S</i> 410.27 X
1	DOOR HANDLE OUTER FRT RH	\$	<i>S</i> 477.76 X
1	DOOR HANDLE MODULE FRT RH	\$	<i>S</i> 133.60 X
1	DOOR REGULATOR FRT RH	\$	<i>D</i> 505.19 ✓
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>J</i> 796.46 ✓
1	DOOR HINGE UPPER FRT RH	\$	<i>R</i> 261.28 X
1	DOOR HINGE LOWER FRT RH	\$	<i>R</i> 300.55 X
1	DOOR PANEL REAR RH	\$	<i>B</i> 2,844.66 ✓
1	DOOR WEATHERSTRIP REAR RH	\$	<i>S</i> 311.60 X
1	DOOR HANDLE MODULE REAR RH	\$	<i>S</i> 133.40 X
1	DOOR HANDLE OUTER REAR RH	\$	<i>S</i> 42.10 X
1	DOOR REGULATOR REAR RH	\$	<i>R</i> 450.60 X
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>R</i> 758.10 X
1	DOOR HINGE UPPER REAR RH	\$	<i>R</i> 241.60 X
1	DOOR HINGE LOWER REAR RH	\$	<i>R</i> 169.90 X
1	ROCKER PANEL OUTER RH	\$	<i>B</i> 1,184.99 ✓
		\$	13,799.92
		10% \$	1,379.99
		\$	12,419.93

Special Nett

1	FENDER CLIP	\$	<i>nn</i> 60.00 X
1	DOOR TRIM CLIP	\$	<i>nn</i> 70.00 X
1	DOOR SEAL CLIP	\$	<i>nn</i> 65.00 X
1	DOOR MOULDING CLIP	\$	<i>nn</i> 70.00 X
1	DOOR STICKER TRANSCAB	\$	<i>nn</i> 100.00 <i>60.50</i>

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD95K

1	DOOR STICKER 65553333	\$	<i>nn</i> 100.00	<i>60sn</i>
1	DOOR STICKER CLASSIC	\$	<i>nn</i> 100.00	<i>30sn</i>
2	WINDSCREEN SEALANT	\$	<i>nn</i> 150.00	<i>X</i>
1	WINDSCREEN MOULDING	\$	<i>nn</i> 200.00	<i>X</i>
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 130.00	<i>X</i>
TOTAL		\$	1,045.00	
TOTAL PARTS		\$	13,464.93	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>1100</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>700</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>90</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20</i>
TOTAL	\$	10,240.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD95K

AAD2112-

Over All Total \$ 36,124.85

(LUMP SUM)

Repair Days

~~20 DAYS~~

6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: