

AUTO PTE LTD
 9 KAKI BUKIT #01-49 SINGAPORE 415875
 4457
 65 64524584
 g No: 201929175W

Estimate

Vehicle No: WC3739U
 Model and make: ISUZU / CYH52S
 Chassis:

Qty Spare parts

List price

- 1 Rear axle housing
- 1 Rear axle housing shaft gasket
- 1 Rear axle housing shaft
- 1 Rear axle housing shaft oil seal (inner)
- 1 Rear axle housing shaft oil seal (outer)
- 1 Rear RH wheel bearing (inner)
- 1 Rear RH wheel bearing (outer)
- 1 Rear RH wheel bearing retainer oil seal
- 1 Rear RH wheel bearing lock plate
- 1 Rear RH wheel bearing lock nut
- 1 Rear RH wheel bearing hub
- 1 Rear RH leaf spring
- 2 Rear RH leaf spring bush
- 1 Rear RH leaf spring shackle (front)
- 1 Rear RH leaf spring shackle (rear)
- 2 Rear RH leaf spring centre U-bolt
- 4 Rear RH leaf spring centre U-bolt lock nut
- 1 Rear RH shock absorber
- 1 Torjan carrier assy
- 2 Rear RH tor rod
- 1 Rear RH brake vacuum pump
- 2 Rear RH brake vacuum pump high pressure hoses

\$ 2400.00 41,350.50 BT
 \$ √22.30 NECV
 \$ 2,676.00 NDX
 \$ √31.80 } NECV
 \$ √22.70 }
 \$ 140.00 345.80 } JMV
 \$ √120.78 }
 \$ √260.40 NECV
 \$ √22.50 NECV
 \$ √66.00 NECV
 \$ 1,590.00 NDX
 \$ 3,678.00 NDX
 \$ 320.70
 \$ 545.80
 \$ 545.80
 \$ 244.00
 \$ 104.00
 \$ 448.00 NDX
 \$ 4,805.00
 \$ 790.00 2,884.00 BT
 \$ 2,810.60
 \$ 640.00

\$ 3476.48 33,534.68
 -10% \$ 347.65 3,353.47
 \$ 3128.83 30,181.21

Qty Spare parts

Special nett price

- 1 Rear under-run bumper
- 1 Rear under-run bumper RH bracket
- 1 Rear under-run bumper LH bracket
- 1 Rear number plate
- 1 Rear number plate lamp
- 1 RH taillamp
- 1 RH taillamp bracket
- 1 Tailamp wire harness
- 1 RH rear wheel mudguard
- 1 RH rear wheel mudguard mudflap

\$ 1300.00 1,800.00 BT
 \$ 550.00 BT
 \$ 550.00 NDX
 \$ 70.00 }
 \$ 155.00 } NDX
 \$ 358.00 } DLV
 \$ √220.00 }
 \$ 835.00 NDX
 \$ √1,600.00 BT
 \$ √220.00 BT

- 1 RH rear wheel mudguard bracket
- 1 Ladder assy
- 1 Ladder lower bracket
- 1 RH rear rim (outer)
- 1 RH rear tyre (outer)
- 1 RH rear rim (inner)
- 1 RH rear tyre (inner)
- 1 Gear oil
- 1 Brake fluid
- 1 Open / closed switch motor assy
- 1 Open / closed switch motor bracket

\$ 220.00	380.00	BTU
\$ 800.00	3,850.00	BTU
\$	✓ 220.00	BTU
\$ 600.00	680.00	BTU
\$ 360.00	500.00	CUT ✓
\$	680.00	NDX
\$ 360.00	500.00	CUT ✓
\$	220.00	
\$	120.00	
\$	2,250.00	NNX
\$	225.00	

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 200.00 3,200.00 ✓

Spray painting on affected panels

\$ 600.00 1,800.00 ✓

Check wiring and lighting system

\$ 480.00

Apply rust coating chemical on affected panels

\$ 280.00

Remove and replace rear undercarriage parts to assist repair

\$ 1,600.00

Conduct and adjust wheel alignment system

\$ 350.00

Remove, reinstall, replace and re-adjust rear axle housing gears to new axle housing

\$ 750.00

Remove, check and reinstall air compressor hoses to assist repair

\$ 350.00

Remove, check and replace rear wire harness to assist repair

\$ 220.00

2,600.00

Survey & Resurvey
28/12/2021
12/15 hrs
T. Min

Lump sum repair
Repair days 10

Total: \$ 54,894.21

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T. Min
10/1/2022