

Co Reg No : 199405410K

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Mr Ang Kok Peng		
	Reg No/Reg Date	SBB266R / 19/08/202		
	Date In/Mileage	/ 0		
	Chassis No	KNAF3416MM5107363		
	Engine No	G4FGMH703099		
	Make/Mode1	KIA/CERATO 1.6 A EX G730		
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK		

Account No Terms Date	/Time Printed	CSE	Operator	TEL COME	WIP No	-	
	2/2021/ 10:08	BLK	282 / Kevin Leong	AWAY.	44431		
	cription of Goods	/ Services		Qty	Unit Price	Disc%	Amount /
E PNT88000 REPLACE FRTBUMPER, BOD E PNT98000 PAINT WORK ON FRT BUMP E PNT88000 REMOVE & INSTALL FRT B M SUNDRY TO APPLY SEALANT ON AF A 54900099 CHECK WIRING & ELECTRI A 10028901 TO CARRY OUT DIAGNOSTI M SUNDRY SUNDRY SUNDRIES M LAMP ASSY-HEAD, LH M COVER-FR BUMPER CA M GRILLE-FRONT BUMPER, M MOULDING-FRONT BUMPER, M LAMP ASSY-SIDE REPEATER M ABSORBER-FRONT BUMPER, M AIR DUCT-FR BUMPER, LH M BRACKET-FR BUMPER UPR S M NEW K3 2020 BODYKIT MAR	PER & BODY KIT  FECTED AREA  CAL SYSTEM  C CHECKLON FLECT  LH CAL SYSTEM  R, LH SOZ KAN  ENERGY Z KAN  SIDE MTG Z KAN	AREA	30 28/12/ 1	Water Const	* * * * * * * * * * * * * * * * * * *	20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00 20.00	114.40/ 67.20 11.20 17.60
Confirm & accepted by		the following relafter spray pail led part(s) during subject to confirm y is on a "Withou ation(s) is allowed em(s) must be re- approval from in	nting resurvey nation t Prejudice" basis				
Continua a accepted by	Acknowledged by F Signature: Date:	Repairer		7% GST on	Ne 6053.		6,053.80 423.77 6,477.57
Authorized signatory and co	ompany stamp				rtai rayab		3,377.07

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or change. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing