

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.  
Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 30 Dec 2021

## **Preliminary Advice**

Vehicle No	: SBB266R	Accident Date	: 23/12/2021
Make	: KIA CERATO	Policy No.	: 7210093332
Assignment Date	: 28/12/2021	Excess	: S\$300.00
Date of Inspection	: 28/12/2021	Est. Duration of Repair	: 3
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,053.80
Revised Amount	:S\$	4,905.40
Check Items (Estimated)	:S\$	338.40
Total	:S\$	5,243.80
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	54,503.00
Salvage Value	:S\$	

Margin for Repair

:S\$ 41,497.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.