



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202048

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 08/04/2022  
Reference CC6/CTI21013202/Kpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SMY 1867Z  
Insured Veh. SMC 7687C  
Claim No. SNM21D207619/C02  
Policy No. DMPCSNW00107512101  
Accident Date 27/12/2021  
Inspection Date 28/12/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21013202/Kpa3q2	
			Date: 08/04/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMC 7687C	Veh. Inspected	SMY 1867Z	
Policy No.	DMPCSNW00107512101	Coverage (\$)	0.00	
Claim No.	SNM21D207619/C02	Excess (\$)	0.00	
Assign From		Assign Date	28/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JTDKB3FUX03093011	Colour	METALLIC PEARL WHITE	
Odometer	69395 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FIRENZA	8 mm	
L/H Front Tyre	195/65 R15	FIRENZA	8 mm	
R/H Rear Tyre	195/65 R15	FIRENZA	8 mm	
L/H Rear Tyre	195/65 R15	FIRENZA	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/12/2021	Inspection Date	28/12/2021	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 1867Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (UPPER)	BUCKLED	485.60	485.60
1	REAR BUMPER (LOWER)	DENTED / CUT	394.50	394.50
12	REAR BUMPER CLIPS @\$4.50	NECESSARY	54.00	54.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	332.70	-
	LESS 25% DISCOUNT		-316.70	-233.52
			950.10	700.58
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
			350.00	-
	<b><u>LABOUR</u></b>			
	TO INSTALL REVERSE SENSOR .		40.00	40.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		300.00	200.00
	SPRAY PAINTING ON AFFECTED & REPLACED PARTS.		300.00	220.00
			640.00	460.00
<b>GRAND TOTAL</b>			<b>1,940.10</b>	<b>1,160.58</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,160.58</b>

Report Ref No. CC6/CTI21013202/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMY 1867Z

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SMY 1867Z

### RE-INSPECTION

