

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

Auto & General Insurance (Singapore) Pte. Ltd
trading as Budget Direct Insurance
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924
Tel: 6221 2199

Veron.

Quotation

DATE : 04.01.2022
VEH NO : GBG6339Z
MODEL : Nissan NV200
D O A : 25.12.2021
YR REF : SJC9215D

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBG6339Z (NISSAN NV200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	<u>LIST ITEMS</u>		
1	Rear Bumper <i>deboned</i>	1	632.20 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	86.60 ✓
3	Rear Bumper Sponge <i>could</i>	1	128.50 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	85.00 x
5	Rear End Panel <i>Dented</i>	1	485.20 ✓
6	Rear End Panel Top Garnish <i>new</i>	1	128.40 x.
7	Tail Lamp - LH & RH <i>new</i>	2	517.40 x.
8	Tailgate - LH <i>Dented</i>	1	1,545.00 ✓
9	Tailgate Lower Lock - LH <i>2nd</i>	1	159.30 ✓
10	Nissan Logo <i>3 new</i>	1	64.90 ✓
11	NV200 Emblem <i>3 new</i>	1	163.50 ✓
12	Tailgate Frame Weatherstripe <i>new</i>	1	215.00 x
			4,211.00
			(842.20)
			\$ 3,368.80

Less ~~20%~~ 10%

S/NETT ITEMS

1	Rear Number Plate <i>3 new</i>	1	30.00 x
2	Rear Number Plate Holder <i>new</i>	1	30.00 x
3	Rear Bumper Clips <i>new</i>	1	30.00 ✓
4	Reverse Sensor <i>2nd</i>	1	280.00 200
5	Rear End Panel Top Garnish Clips <i>new</i>	1	20.00 x.
6	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
7	Tailgate Glass Sealant <i>new</i>	1	60.00 40.
8	Tailgate Advertisement Stickers - LH <i>new</i>	1	200.00 120.
			\$ 710.00

450

RE : ESTIMATE FOR ACCIDENT REPAIR GBG6339Z (NISSAN NV200)

Total parts \$ 4,078.80

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 700.
2	To putty & spray up paint works	\$	1,000.00 500
3	To check wiring system	\$	50.00 30.
4	To spray tuff coat	\$	150.00 60
5	To remove rear upholstery	\$	150.00 30.
6	To transfer tailgate fittings - LH	\$	150.00 60
7	To remove reverse sensor	\$	100.00 50
8	To remove tailgate glass - LH	\$	100.00 60.

Total Labour \$ 2,900.00

Grand Total **\$ 6,978.80**

7399.90

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 4878.68
h/s: 3.9K.
05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: