



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/1
Our Ref : RP0004/01/22 Date : 05/01/2022

SUPPLEMENTARY

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVEUNE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 2399924

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SKZ6388A - HONDA STEPWAGON
INSURED : CHIU LI CHUAN
DATE OF ACCIDENT : 24/12/2021
POLICY NO : MP309724

ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear boot keyless sensor	10	187.80	187.80	187.80
2 rear boot lower rubber seal garnish	10	249.00	249.00	249.00
				436.80
Less 20%				-87.36
Total Material				\$349.44
Nett Total Before Gst				\$349.44

Your faithfully

NPH AUTO SERVICE
(Manager)