

Figure D-1: MID21831 Vehicle Plate Dislodged



Figure D-2: MID 21831 Front View (Zoomed In)



Figure D-3: MID 21831 Steering Column (Zoomed In)



Figure D-4: MID 21831 Centre Cabin Panel (Zoomed In)



Figure E-1: XD3474R (Rear View)

ANNEX C




Figure C-1: MID 21831 Moving Along Lim Chu Kang Rd




Figure C-2: Intended Route of XD3474R




Figure C-3: XD3474R Came into a Complete Halt due to Oncoming Traffic




Figure C-4: MID 21831 Collided into XD 3474R

SINGAPORE ARMED FORCES STATEMENT OF DRIVER/WITNESS

DIALECT LANGUAGE SPOKEN ENGLISH, MALAY TEL NO ADDRESS DY RECORDED BY TAN ZHI YUAN RANK LIT TIME 1530 DATE 23/12/2021 SIGN JATE LANGUAGE SPOKEN RECORDED BY TAN ZHI YUAN RANK LIT TIME 1530 DATE 23/12/2021 SIGN JATE LANGUAGE RECORDED BY TAN ZHI YUAN RANK LIT TIME 1530 DATE 23/12/2021 SIGN JATE LANGUAGE RECORDED BY TAN ZHI YUAN RANK LIT TIME 1530 DATE 23/12/2021 SIGN JATE AND AND AND AND AND AND AND AN												
EMPLOYMENT NSF DRIVING LICENCE NO SAF/TPT/N/01910/23 NATIONALITY SINGAPOREAN DIALECT LANGUAGE SPOKEN ENGLISH, MALAY TEL NO ADDRESS INTERPRETED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN RECORDED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN I, TXXXX927Z, CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI was supporting and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	STATEMENT OF	CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI						ALIASES		NIL		
DIALECT LANGUAGE SPOKEN ENGLISH, MALAY TELNO ADDRESS DITERPRETED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN J. TXXXX927Z, CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI was supporting and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	NRIC NO	927Z	927Z AGE			20		MALE/FEMALE		MALE		
ADDRESS INTERPRETED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN RECORDED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN I, TXXXX927Z, CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI was supporting and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say.	EMPLOYMENT	NSF	1	ICENCE	SAF/TPT/N/01910/23		NATIONALITY		SINGAPOREAN			
INTERPRETED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN RECORDED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN I, TXXXX927Z, CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI was supporting and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	DIALECT			E	ENGLISH, MALAY		TEL NO					
RECORDED BY TAN ZHI YUAN RANK 2LT TIME 1530 DATE 23/12/2021 SIGN I, TXXXXY927Z, CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI was supporting and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	ADDRESS											
I, TXXXXY927Z, CPL MUHAMMAD NUR ALAM SHAH BIN RAZALI was supporting and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	INTERPRETED BY	TAN ZHI YUAN	RANK	2LT	TIME	1530	DATE	23/12/2021	SIGN	3/2-		
and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	RECORDED BY	TAN ZHI YUAN	RANK	2LT	TIME	1530	DATE	23/12/2021	SIGN	72-		
moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	I, TXXXX927Z, CF	L MUHAMMAD	NUR ALA	M SHAI	I BIN RA	ZALI was	supportin	g				
moved out with Vehicle Commander (VC), 3SG LEE JUN WEI, from STW ETI. Around 1030H, I came in contact with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/										-		
with the rear of a civilian lorry (XD3474R) along Lim Chu Kang road heading to Sungei Gedong Camp. Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	and was driving a 6	and was driving a 6 Tonner (MID 21831). After No Move timing, I did my Before Operational Service (BOS) and										
Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	moved out with Veh	icle Commander (\	/C), 3SG I	EE JUN	WEI, fro	m STW E	TI. Around	1030H, I	came in co	ntact		
Before I made contact with the lorry, I was at least 75-100m behind it. After the left bend. I saw the lorry in front slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/	with the rear of a civ	rilian lorry (XD347	4R) along	Lim Chu	Kangroa	d haading	to Sungai	Gadona C	amn			
slowed down, but it was still quite a distance, and it also started raining, so I on the wiper. As I got closer, I thought the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER/										ont		
the lorry in front will move off as the opposite lane is cleared, so I continued driving. When I realise that the lorry came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the lorry. That is all I have to say. SIGNATURE OF DRIVER 23/12/0021 SIGNATURE OF DRIVER		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			-				,	-		
came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the long. That is all I have to say. SIGNATURE OF DRIVERY According to the same of the sa	slowed down, but it	was still quite a dis	tance, and	it also st	arted raini	ng, so I or	the wiper	r. As I got o	loser, Ith	ought		
came to a complete stop, that is when I reduced my speed and executed emergency break, then I collide into the long. That is all I have to say. SIGNATURE OF DRIVERY According to the same of the sa	the lorry in front wil	l move off as the o	oposite lan	e is clear	ed. so I co	ontinued d	riving. Wh	en I realise	that the l	onv		
lorry. That is all I have to say. DATE 23/12/2021 SIGNATURE OF DRIVER/												
DATE 23/12/2021 SIGNATURE OF DRIVER/	came to a complete	stop, that is when i	reduced m	y speed a	ina execui	ed emerge	ency oreas	, then I col	nde into ti	ie		
DATE 23/12/2021 - KW//	lorry. That is all I have to say.											
DATE 23/12/2021 - KW//												
DATE 23/12/2021 - KW//												
DATE 23/12/2021 - KW//												
DATE 23/12/2021 - KW//												
DATE 23/12/2021 - KW//												
DATE 23/12/2021 - KW//												
WIINESS	DATE	23/12/2021	1	SIGNA	TURE OF D WITNESS			4	200			

I (Personal Particulars)

Accused							
Rank/Name	3S	G Lee Jun	Wei		Appt	Adn	nin Spec/ STW
NRIC No		478	I		Unit	ETI	STW
Age		19	Sex	M	Vocati	on	Combat Engineer
Types of Servi	ce	NSF	DOE	050121	ORD		041122

II (STATEMENT)

I, 3SG Lee Jun Wei, 478I was a vehicle commander for a 6 Tonner (MID 21831) going from Nee Soon Camp to Sungei Gedong Camp at 0945, to collect outration to support The TO of the vehicle was CPL Alam, there were also 2 passengers, REC Shawn Peh and REC Seah Yong Kang. As we were nearing Sungei Gedong Camp, we entered Lim Chu Kang Road, a 2 way, 2 lane road. There was construction happening on our lane for a small portion the road. There were thus cones laid out around the construction site, in front of the cones was a stationary civilian heavy vehicle. At 1030, as we were approaching the civilian heavy vehicle, within the braking distance of roughly 10m, I realized that the TO, CPL Alam, did not slow down at all and was still travelling at the speed before, (around 40-50km/h). However, it was too late before I could get him to perform an emergency break. At around 2m, the TO executed the emergency brake, but it was too late and we crashed into the civilian heavy vehicle. After the crash, we both dismounted and quickly got the 2 passengers down as well. There were minor injuries sustained by everybody onboard the 6 tonner. For the passengers REC Shawn and REC Seah, they both sustained minor bruises at their hips. The TO CPL Alam sustained minor bruises at shin. I sustained minor bruises on my shin and knees. At around 1035hrs, we set up the hazard sign roughly 20m behind the tonner and immediately reported to Ops room as well as RSM of the live firing. I called my RSM 2WO Lim Boon Seng and ops room while CPL Alam called his ops warrant. CPL Alam also took photo of the truck and license of the truck driver. The truck driver drove off at around 1050hrs. At around 1200hrs, REC Shawn and REC Seah was picked up by MAJ Tay Choon Ngai, CO ECTS. The recovery car and tonner came at around 1212hrs. I went back to Nee Soon Camp in the replacement tonner.

B-1 RESTRICTED \ SENSITIVE NORMAL

RESTRICTED \ SENSITIVE NORMAL

This statement is written to the best of my knowledge.

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

Police Statio Yishun Sout	h N.P.C						1000000	1224/2014 1 c 1 No. T/20211224/20	
32 Yishun S Tel No: 1800	treet 81 SIN 0-8522999	GAPORE 7684	456				кера	CN0. 1/20211224/20	
REPORT OF A	TRAFFIC AC	CIDENT							
	Report Made		Vide	Report No	V4			Station Diary No	
Informant's	Particular		_				2	.7	
Name of Inf	ormant:		Addr	ess:					
MUHAMMA RAZALI	D NUR ALA	M SHAH BIN							
ID Type / ID			Cont	act No.:					
NRIC NO /	927Z		Hom	e/Office:		Mobile	-		
Nationality: SINGAPOR	E CITIZEN		Ema	il;					
Sex: Age: Date of Birth: Male 20 18/07/2001			Type of Informant:						
Race:				TOTAL STREET,			nstitution / School Name:		
Javanese Occupation			Desir	11-					
	rvice Full Tir	me	Class	ng Licence s: 3.4	Information:	Date of	Evnin	r	
Type of Accident:	Non-	the Accident Injury Inment Vehicle		Drink Drive: No	Date/Tii Accider			Type of Location Straight Road	
Location:				1140	23/12/2	021.10.30			
	ANG ROAD								
	Number: 17		Door	10.1					
Weather: Drizzling			Wet	Road Surface: Wet			Road Speed Limit:		
Drizzling	Traffic Flow: Two Way				Traffic Control: Not Controlled				
Drizzling Traffic Flow			Not (Jontrolled			Light	Anyone conveyed by ambulance:	
Drizzling Traffic Flow Two Way Type of Col	lision:	es - Head To R		Jontrolled			ambu	ance.	
Drizzling Traffic Flow Two Way Type of Coll Between Mo	lision: oving Vehicle			Jontrolled			ambu No	iance.	
Drizzling Traffic Flow Two Way Type of Coll Between Mo	lision: oving Vehicle	lved			Color		No No		
Drizzling Traffic Flow Two Way Type of Coll Between Mo	lision: oving Vehicle			Model	Color		ambu No adition	No of Passeng	
Drizzling Traffic Flow Two Way Type of Col Between Mo Details of V Vehicle No. MID21831	lision: oving Vehicle /ehicle Invo Type Lorry	lved			Color	Slig Dan	No No	No of Passeng	
Drizzling Traffic Flow Two Way Type of Coll Between Mo	ision: oving Vehicle 'ehicle Invo	lved			Color	Slig Dan No	No No idition	No of Passeng	
Drizzling Traffic Flow Two Way Type of Col Between Mo Details of V Vehicle No. MID21831 XD3474R	lision: oving Vehicle /ehicle Invo Type Lorry	lved Make			Color	Slig Dan No	No No adition htly naged	No of Passeng	



Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999



Report No. T/20211224/2014

CONTINUATION OF REPORT

Driver							
Name	MUHAMMAD NUR RAZALI	ALAM SH	ID No.		927Z		
Related Vehicle	MID21831 (Lorry)		Contact No				
Hospital/Clinic	NIL				s of ng nce & ry Date	Class: 3,4 Date of Expiry: NIL	
Date Treatment	NIL		Data Disa	-April	y Date		
No. of Days gran	Date Disc	narge	NIL				
Driver	Degree o	rinjury	NIL				
Name	Subramanian Rame	ch		-			
				ID No.		357Q	
Related Vehicle	XD3474R (Lorry)					70,70,70,790	
	ADDATAN (LONY)		Contact No.				
Hospital/Clinic	NIL						
	NIL		Class of Driving Licence &		Class; NIL Date of Expiry: NIL		
Date Treatment	NIL		0	Expiry	_		
No. of Days gran	ted Medical Leave	NIL	Date Disci	scharge NIL			
Passenger		IVIL	Degree of	Injury	NIL		
Name	Lee Jun Wei				70		
NAME OF THE PARTY				ID No.		NIL	
Related Vehicle	NIL						
		Contact No.					
Hospital/Clinic	NIL			Constitution (Constitution)			
30.700.700.700.700.00	11112			Driving Licence &		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		15.5	Expiry	The second second		
	ed Medical Leave	NIL	Date Disch	arge	NIL		
	TOUTE	TAIL	Degree of	Injury	NIL		

Brief Details.

On 23/12/2021 at about 10.30AM, I was driving a 6 tonner (MID21831) along Lim Chu Kang road towards Sungei Gedong camp, I observed that there was one vehicle (XD3474R) in front of me the distance between my vehicle and his was about 75M to 100M. I also observed that the vehicle XD3474R is slowing down, however when I was closer to the vehicle I thought that XD3474R will move off, instead XD3474R came to a complete stop. Then I tried to execute an emergency brake, however the vehicle could not stop in time and my vehicle MID21831 collided on to the rear of XD3474R. After I alighted from my vehicle MID21831, I realize that there was a construction works on the road. After which I made a check on my passenger and they are alright and do not require any medical assistance.

After which I proceed to speak to the driver namely Mr Subramanian Ramesh 357Q of XD3474R and he is alright also hence I did not seek for medical assistance. After exchanging of particulars I left the





Police Station Of Origin: Yishun South N.P.C 32 Yishun Street 81 SINGAPORE 768456 Tel No: 1800-8522999 3 of 4 Report No. 1/20211224/2014

CONTINUATION OF REPORT

accident site.

I would like to inform that I have a total of 3 passenger 1 of them is my vehicle commander namely 3SG Lee Jun Wei and the other 2 passenger that was seated at the back I do not have their particulars.

There was no traffic police or ambulance activated as well.

My vehicle was installed with a dash camera, I have the footage of the accident as well.