

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: MITSUBISHI FV51JJD4RDEA

Engine/Chassis No.: FV51JJA00464


Date of accident:

Damaged area: Rear

Date: 04/02/2022

Claim Type: TP

VRN: XD3474R



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear cargo door	2	\$ 7,897.00	\$ 15,794.00
2	Rear cargo door hinge	4	\$ 368.00	\$ 1,472.00
3	Rear cargo door lock carrier	1	\$ 563.00	\$ 563.00
4	Rear cargo door lock bar	1	\$ 183.00	\$ 183.00
5	Rear cargo door lower member	1	\$ 9,358.00	\$ 9,358.00
6	Rear cargo door lower member lock carrier	1	\$ 445.00	\$ 445.00
7	Rear cargo door lower member pipe hook	2	\$ 175.00	\$ 350.00
8	Rear cargo door lower member hinge	2	\$ 577.00	\$ 1,154.00
9	Driver seat assy	1	\$ 3,850.00	\$ 3,850.00
Subtotal				\$ 33,169.00
List discount				25.00%
Total				\$ 24,876.75

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear number plate	1	\$ 55.00	\$ 55.00
2	Rear number plate lamp bulb	1	\$ 15.00	\$ 15.00
3	Rear cargo door "60km/h" sticker n/s	1	\$ 25.00	\$ 25.00
4	Rear cargo door "HOW'S MY DRIVING" sticker n/s	1	\$ 180.00	\$ 180.00
5	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 325.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	10	\$ 2,000.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	9	\$ 1,800.00
4	To rust proof all affected portions after repair.	1	\$ 200.00
Total labour			\$ 4,050.00
Estimate Grand Total			\$ 29,251.75