

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SJB 1953 P**
Model : Porsche Cayman
Year : 2008
Chassis No : WPOZZZ98Z8U751028

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	WS recommended	Your recommendation
1	Rear bumper	1	\$ 3,798.30	\$ -
2	Rear bumper side retainer	2	\$ 132.20	\$ 264.40
3	Rear bumper bracket	2	\$ 198.80	\$ -
4	Rear fender RH	1	\$ 5,835.40	\$ 5,835.40
5	Rear fender inner cowling RH	1	\$ 448.30	\$ 448.30
6	Rear fender air vents garnish RH	1	\$ 478.90	\$ 478.90
7	Rear fender inner trim board RH	1	\$ 580.40	\$ -
8	Front door RH	1	\$ 3,658.60	\$ -
9	Front door weatherstrip RH	1	\$ 447.60	\$ -
10	Front door outer handle RH	1	\$ 578.30	\$ -
11	Side mirror assy RH	1	\$ 1,822.56	\$ -
12	Roker panel RH	1	\$ 3,722.50	\$ 3,722.50
13	Taillamp RH	1	\$ 1,078.60	\$ -
14	Taillamp lower bracket RH	1	\$ 154.00	\$ -
15	Exhaust pipe	1	\$ 4,800.00	\$ 4,800.00
16	Exhaust Muffler Valve	1	\$ 3,650.00	\$ -
17	Exhaust Muffler Mounting	6	\$ 128.00	\$ -
18	Exhaust Heat Shield	1	\$ 733.00	\$ 733.00
19	Rear lower arm	2	\$ 2,820.40	\$ 5,640.80
20	Rear control arm	2	\$ 789.30	\$ 1,578.60
21	Rear trust arm	2	\$ 853.20	\$ 1,706.40
22	Rear shock absorber	2	\$ 2,622.10	\$ 5,244.20
23	Rear knuckle arm	2	\$ 1,645.50	\$ 3,291.00
24	Rear Knuckle arm bearing	2	\$ 598.50	\$ 1,197.00
25	Rear upper arm	2	\$ 788.10	\$ 1,576.20
26	Rear crossmember	1	\$ 2,513.50	\$ 2,513.50
27	Rear ABS sensor	2	\$ 492.90	\$ 985.80
			Parts Sub Total :	\$ 40,016.00
10%			Discount :	\$ 4,001.60
			PARTS TOTAL :	\$ 36,014.40

Nos.	SPECIAL NETT	Qty	WS recommended	Your recommendation
1	Sundries	1	\$ 80.00	\$ -
2	Rear bumper clips	1	\$ 50.00	\$ -
3	Rear bumper reverse sensor	2	\$ 250.00	\$ -
4	Rear fender sealant	1	\$ 100.00	\$ 40.00
5	Rear fender inner cowling clips	1	\$ 50.00	\$ -
6	Rear fender inner trim board clips	1	\$ 50.00	\$ -
7	Front door sealant	1	\$ 100.00	\$ -
8	Side mirror assy seal	1	\$ 60.00	\$ -
9	Rocker panel sealant	1	\$ 100.00	\$ 30.00
10	Taillamp seal	1	\$ 60.00	\$ 20.00
11	Taillamp clips	1	\$ 50.00	\$ -
12	Original Porchse Paint Protection Film	2	\$ 750.00	\$ 1,500.00
13	Rear alloy rim	2	\$ 1,450.00	\$ 2,900.00
14	Rear tyre	2	\$ 680.00	\$ 1,360.00
SPECIAL NETT TOTAL :				\$ 5,850.00

Nos.	LABOUR	S\$
1	R&R rear bumper reverse sensor	\$ -
2	R&R front door component	\$ -
3	R&R rear under carriage	\$ 250.00
4	R&R rear tyre and balancing	\$ 60.00
5	R&R Exhaust Pipe	\$ 80.00
6	Wheel alignment	\$ 60.00
7	Check wiring	\$ -
8	Uphostery	\$ -
9	Conduct water leak test	\$ -
10	Diagnostic reset fault code	\$ 120.00
11	Panel beating	\$ 1,600.00
12	Rust proofing	\$ -
13	Spray painting	\$ 400.00
LABOUR TOTAL :		\$ 2,570.00

Supplementary = \$3380.40
 (Labour+S/N+Part) = \$44434.40
 L/S less 20% = \$39956.00
 Total \$38,251.80 and repair 21 days

PARTS TOTAL : \$ 36,014.40
 SPECIAL NETT TOTAL : \$ 5,850.00
 LABOUR TOTAL : \$ 2,570.00
GRAND TOTAL : \$ 44,434.40