

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Vehicle Nos : **SJB 1953 P**

Date of Survey :

Model : **Porsche Cayman**

Date of ReSurvey:

After-Paint:Year : **2008**

Contacts :

Chassis No : **WPOZZZ98Z8U751C***** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 3,798.30	\$ 3,798.30
2	Rear bumper side retainer	2	\$ 108.75 132.20	\$ 217.50 264.40
3	Rear bumper bracket	2	\$ 198.80	\$ 397.60
4	Rear fender RH	1	\$ 5,835.40	\$ 2160.00 5,835.40
5	Rear fender inner cowling RH	1	\$ 448.30	\$ 158.60 448.30
6	Rear fender air vents garnish RH	1	\$ 478.90	\$ 290.00 478.90
7	Rear fender inner trim board RH	1	\$ 580.40	\$ 580.40
8	Front door RH	1	\$ 3,658.60	\$ 3,658.60
9	Front door weatherstrip RH	1	\$ 447.60	\$ 447.60
10	Front door outer handle RH	1	\$ 578.30	\$ 578.30
11	Side mirror assy RH	1	\$ 1,822.56	\$ 1,822.56
12	Roker panel RH	1	\$ 3,722.50	\$ 819.61 3,722.50
13	Taillamp RH	1	\$ 1,078.60	\$ 1,078.60
14	Taillamp lower bracket RH	1	\$ 154.00	\$ 154.00
15	Exhaust pipe	1	\$ 1460.00 4,800.00	\$ 1460.00 4,800.00
16	Exhaust Muffler Valve	1	\$ 3,650.00	\$ 3,650.00
17	Exhaust Muffler Mounting	6	\$ 128.00	\$ 768.00
18	Exhaust Heat Shield	1	\$ 733.00	\$ 285.00 733.00
19	Rear lower arm	2	\$ 980.00 2,820.40	\$ 1960.00 5,640.80
20	Rear control arm	2	\$ ✓ 789.30	\$ ✓ 1,578.60
21	Rear trust arm	2	\$ ✓ 853.20	\$ ✓ 1,706.40
22	Rear shock absorber	2	\$ 1405.10 2,622.10	\$ 2810.20 5,244.20
23	Rear knuckle arm	2	\$ 1,645.50	\$ ✓ 3,291.00
24	Rear Knuckle arm bearing	2	\$ 350.00 598.50	\$ 700.00 1,197.00
25	Rear upper arm	2	\$ ✓ 788.10	\$ ✓ 1,576.20
26	Rear crossmember	1	\$ 2,513.50	\$ ✓ 2,513.50
27	Rear ABS sensor	2	\$ 492.90	\$ ✓ 985.80

Parts Sub Total : \$ 56,949.96

20%

Discount \$ 11,389.99

PARTS TOTAL : \$ 45,559.97

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Rear bumper clips	1	\$ 50.00	\$ 50.00
3	Rear bumper reverse sensor	2	\$ 250.00	\$ 500.00
4	Rear fender sealant	1	\$ 100.00	\$ 40.00 100.00
5	Rear fender inner cowling clips	1	\$ 50.00	\$ 50.00
6	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00
7	Front door sealant	1	\$ 100.00	\$ 100.00
8	Side mirror assy seal	1	\$ 60.00	\$ 60.00
9	Rocker panel sealant	1	\$ 100.00	\$ 30.00 100.00
10	Taillamp seal	1	\$ 60.00	\$ 20.00 60.00
11	Taillamp clips	1	\$ 50.00	\$ 50.00
12	Original Porchse Paint Protection Film	2	\$ 750.00	\$ ✓ 1,500.00
13	Rear alloy rim	2	\$ 1,450.00	\$ ✓ 2,900.00
14	Rear tyre	2	\$ 480.00 680.00	\$ 960.00 1,360.00

SPECIAL NETT TOTAL : \$ ~~5450.00~~ 6,960.00

Nos.	LABOUR	S\$
1	R&R rear bumper reverse sensor	\$ 100.00
2	R&R front door component	\$ 150.00
3	R&R rear under carriage	\$ 250.00 300.00
4	R&R rear tyre and balancing	\$ 60.00 100.00
5	R&R Exhaust Pipe	\$ 80.00
6	Wheel alignment	\$ 60.00 180.00
7	Check wiring	\$ 100.00
8	Uphostery	\$ 300.00
9	Conduct water leak test	\$ 180.00
10	Diagnostic reset fault code	\$ 120.00 300.00
11	Panel beating	\$ 1600.00 2,200.00
12	Rust proofing	\$ 200.00
13	Spray painting	\$ 400.00 2,000.00

LABOUR TOTAL : \$ ~~2570.00~~ 6,190.00

PARTS TOTAL : \$ 45,559.97

SPECIAL NETT TOTAL : \$ 6,960.00

LABOUR TOTAL : \$ 6,190.00

GRAND TOTAL : \$ 58,709.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Parts 17,609.93
 SN 5,450.00
 Labour 2,570.00
 25,629.93
 @20% 5,125.99
 20503.94

LS 20,500/2

Tatin Min
 8/1/2022

Survey
 28/12/2021
 1A 30hrs
 Tatin Min

Resurvey
 31/12/2021
 1130hrs
 Tatin Min

Lump sum repair
 Repair days > 1