

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :**Date of Survey :****Date of ReSurvey:****After-Paint:****Contacts :****Vehicle Nos : SJB 1953 P****Model : Porsche Cayman****Year : 2008****Chassis No : WPOZZZ98Z8U751C***** AGREED Cost Of Repair and Repair Day/s with SJE *****Amount:****Working Day:**

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear bumper	1	\$ 3,798.30	\$ 3,798.30	NDX
2	Rear bumper side retainer	2	\$ 132.20	\$ 264.40	NECV
3	Rear bumper bracket	2	\$ 198.80	\$ 397.60	NSX
4	Rear fender RH	1	\$ 5,835.40	\$ 5,835.40	DDV
5	Rear fender inner cowling RH	1	\$ 448.30	\$ 448.30	TNV
6	Rear fender air vents garnish RH	1	\$ 478.90	\$ 478.90	MISV
7	Rear fender inner trim board RH	1	\$ 580.40	\$ 580.40	NDX
8	Front door RH	1	\$ 3,658.60	\$ 3,658.60	NDX
9	Front door weatherstrip RH	1	\$ 447.60	\$ 447.60	NDX
10	Front door outer handle RH	1	\$ 578.30	\$ 578.30	
11	Side mirror assy RH	1	\$ 1,822.56	\$ 1,822.56	BRV
12	Roker panel RH	1	\$ 3,722.50	\$ 3,722.50	
13	Taillamp RH	1	\$ 1,078.60	\$ 1,078.60	NDX
14	Taillamp lower bracket RH	1	\$ 154.00	\$ 154.00	NDX
15	Exhaust pipe	1	\$ 4,800.00	\$ 4,800.00	DDV
16	Exhaust Muffler Valve	1	\$ 3,650.00	\$ 3,650.00	NSX
17	Exhaust Muffler Mounting	6	\$ 128.00	\$ 768.00	NDX
18	Exhaust Heat Shield	1	\$ 733.00	\$ 733.00	DDV
19	Rear lower arm	2	\$ 2,820.40	\$ 5,640.80	BTV
20	Rear control arm	2	\$ 789.30	\$ 1,578.60	BTV
21	Rear trust arm	2	\$ 853.20	\$ 1,706.40	BTV
22	Rear shock absorber	2	\$ 2,622.10	\$ 5,244.20	BTV
23	Rear knuckle arm	2	\$ 1,645.50	\$ 3,291.00	DDV
24	Rear Knuckle arm bearing	2	\$ 598.50	\$ 1,197.00	NDV
25	Rear upper arm	2	\$ 788.10	\$ 1,576.20	BTV
26	Rear crossmember	1	\$ 2,513.50	\$ 2,513.50	BTV
27	Rear ABS sensor	2	\$ 492.90	\$ 985.80	BRV
Parts Sub Total :				\$ 56,949.96	
20% Discount				\$ 11,389.99	
PARTS TOTAL :				\$ 45,559.97	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Rear bumper clips	1	\$ 50.00	\$ 50.00
3	Rear bumper reverse sensor	2	\$ 250.00	\$ 500.00
4	Rear fender sealant	1	\$ 100.00	\$ 40.00 100.00
5	Rear fender inner cowling clips	1	\$ 50.00	\$ 50.00
6	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00
7	Front door sealant	1	\$ 100.00	\$ 100.00
8	Side mirror assy seal	1	\$ 60.00	\$ 60.00
9	Rocker panel sealant	1	\$ 100.00	\$ 30.00 100.00
10	Taillamp seal	1	\$ 60.00	\$ 20.00 60.00
11	Taillamp clips	1	\$ 50.00	\$ 50.00
12	Original Porchse Paint Protection Film	2	\$ 750.00	\$ 1,500.00
13	Rear alloy rim	2	\$ 1,450.00	\$ 2,900.00
14	Rear tyre	2	\$ 680.00	\$ 1,360.00
SPECIAL NETT TOTAL :				\$ 6,960.00

Nos.	LABOUR	S\$
1	R&R rear bumper reverse sensor	\$ 100.00
2	R&R front door component	\$ 150.00
3	R&R rear under carriage	\$ 250.00 300.00
4	R&R rear tyre and balancing	\$ 60.00 100.00
5	R&R Exhaust Pipe	\$ 80.00
6	Wheel alignment	\$ 60.00 180.00
7	Check wiring	\$ 100.00
8	Uphostery	\$ 300.00
9	Conduct water leak test	\$ 180.00
10	Diagnostic reset fault code	\$ 120.00 300.00
11	Panel beating	\$ 1600.00 2,200.00
12	Rust proofing	\$ 200.00
13	Spray painting	\$ 400.00 2,000.00
LABOUR TOTAL :		\$ 6,190.00

PARTS TOTAL : \$ 45,559.97
 SPECIAL NETT TOTAL : \$ 6,960.00
 LABOUR TOTAL : \$ 6,190.00
GRAND TOTAL : \$ 58,709.97

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: