

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21013217/R1QF3E2

Date: 21/01/2022

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MC011294		
Claimant Vehicle No :	JSD4117	Insured Vehicle No :	YQ2996C		
Date of Loss:	11/12/2021	Nature of Claim:	TP	Claim No:	M2105769

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JSD4117	Engine No:	HIDDEN
Make & Model:	YAMAHA 135LC, 134cc ES	Chassis No:	PMYUG0420H0080515
Reg. Date:	01/05/2017 (Man. Year: 2017)	Odometer:	64840 km
Colour:	Multi-colour		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,776.00	2,191.50	584.50	21.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	565.00	385.00	180.00	31.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,341.00	2,576.50	764.50	22.88
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	3,341.00	2,050.00	1,291.00	38.64

INSPECTION

Date of Assignment:	28/12/2021		
Date Inspected:	29/12/2021	Inspected At:	Kim Kock Motor Pte Ltd (HQ) Blk 27A Jurong Port Road #01-19 Singapore 619101
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Jan 2022)	
Parts:	N/A	YAMAHA 135LC 134cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JSD4117)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	2		*FRONT FORK R/L	Bent	290.00 F	-	*290.00 FL
2	1		*FRONT FORK BRACKET	Cut	195.00 F	-	*195.00 FL
3	2		*MIRRLE R/L	Scratched	78.00 F	-	*78.00 FL
4	1		*CONE BEARING CENTRAL	Necessary	95.00 F	-	*95.00 FL
5	1		*FRONT FOOT REST ASSY	Bent	85.00 F	-	*85.00 FL
6	1		*REAR MUDGUARD ASSY	Scratched	165.00 F	-	*165.00 FL
7	1		*EXHAUST PIPE FULL STAY	Bent	295.00 F	-	*295.00 FL
8	1		*HANDLE BAR	Bent	115.00 F	-	*115.00 FL
9	1		*HEAD LIGHT	Scratched	98.00 F	-	*98.00 FL
10	2		*HEAD COWING	Cracked	168.00 F	-	*168.00 FL
11	1		*FRONT CENTRAL COVER	Scratched	95.00 F	-	*95.00 FL
12	1		*HEAD LIGHT WISKIM	Not Necessary	28.00 F	-	*- FL
13	1		*NUMBER PLATE FRONT	Not Necessary	18.00 F	-	*- FL
14	1		*FRONT MUDGUARD	Cracked	98.00 F	-	*98.00 FL
15	1		*(L) FRONT SIDE FAILING	Scratched	115.00 F	-	*115.00 FL
16	1		*HANDLE BAR BELESEN	Scratched	58.00 F	-	*58.00 FL
17	1		*REAR TAIL LIGHT ASSY	Scratched	185.00 F	-	*185.00 FL
18	1		*FRONT SPORT RIM ASSY	Repair	295.00 F	-	*- FL
19	1		*REAR SEAT BAR ASSY	Scratched	165.00 F	-	*165.00 FL
20	1		*(L) REAR SIDE FAILING	Cracked	135.00 F	-	*135.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,776.00	2,435.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	243.50
Total Parts (S\$)	2,776.00	2,191.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	35.00	35.00
2	REAR BODY REPAIR	New	250.00	150.00
3	LABOUR	New	280.00	200.00
Gross Labour Cost (\$)			565.00	385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >