

JSD 4117.

H-P87534235

To wiring — \$35 — receipt? / 35

Front Fork R/L \$290 — ? bt ✓

Front Fork Bracket — \$195 — ? cut ✓

MIDDLE R/L — \$78 — sc ✓

COM Bearing Central \$95 — ? ne ✓

Front Foot ~~1st~~ Assy — \$85 — bt ✓

Rear Mudguard Assy — \$165 — sc ✓

Exhaust pipe Full Stem \$295 — bt ✓

Handle Bar — \$115 — ? bt ✓

Head light — \$98 — sc ✓

Head Cowling 2 pc — \$168 — ? ca ✓

Front Central Cover — \$95 — sc ✓

Head light wiskin — \$28 — X17 X

Number plate front — \$18 — X18 X

Front Mudguard 1 pc — \$98 — ca ✓

① Front Side Fairing 1 pc — \$115 — ca/sc ✓

Handle Bar Belesen — \$58 — sc ✓

Rear Tail light Assy — \$185 — sc ✓

Front Sprocket Assy — \$295 — repair X

2135
10%
1921.50

Rear Body Repair — ~~\$250~~ - ~~200~~ 100
150

Rear Seat BAR Assy — \$165.50 ✓ } 300
10%

(1) Rear Side Filing — \$135.00 ✓ } 270

labour

labour — 350

→ ~~200~~ 200

ASUL

Hp 90010068

4 days

L/S

29/12/21 @ 1030

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1921.50

35.00

270.00

350.00

2576.50

20%

2061.20

L/S - \$2,050