

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013218/GQY3Q2**Date:** 02/12/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00151192101

**Claimant Vehicle
No :** SBE3456Z**Insured Vehicle
No :** YN6584Y

Date of Loss: 23/12/2021

Nature of Claim: TP

Claim
No: SNM21D207552/C02/TOHHSDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBE3456Z**

Make & Model: AUDI S5 SPORTBACK, 3.0 TFSI QUATTRO (A)

Engine No: CAK014836

Reg. Date: 08/03/2011 (Man. Year: 2010)

Chassis No: WAUZZZ8F7BN007122

Colour: Grey

Odometer: 91674 km

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35Z R19

Rear Tyre Size: 255/35Z R19

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,432.45	37,598.60	7,833.85	17.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	3,020.00	1,160.00	27.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	49,612.45	40,618.60	8,993.85	18.13
Approved Total (Overridden) (\$\$)		32,400.00		
(\$\$)	49,612.45	32,400.00	17,212.45	34.69
+ GST 7.00/7.00% (\$\$)	3,472.87	2,268.00	1,204.87	34.69
Nett Amount (\$\$)	53,085.32	34,668.00	18,417.32	34.69

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 29/12/2021 Inspected At:

 Vin's Auto Pte Ltd (Vin's Auto)
 Sin Ming AutoCity,, 160 Sin Ming Drive #03-03
 Singapore 575722

Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Dec 2022)

Parts: 143 AUDI S5 SPORTBACK 3.0 TFSI QUATTRO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBE3456Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	2,420.00 FL	*2,420.00 FL
2	1		*REAR BOOTLID EMBLEM	Necessary	95.00 FL	*95.00 FL
3	1		*REAR BOOTLID S5 EMBLEM	Necessary	74.00 FL	*74.00 FL
4	1		*REAR BOOTLID THIRD BRAKE LIGHT	Cracked	235.00 FL	*235.00 FL
5	1		*REAR BOOTLID RH REFLECTOR	Cracked	520.00 FL	*520.00 FL
6	1		*REAR BOOTLID LH REFLECTOR	Cracked	520.00 FL	*520.00 FL
7	1		*REAR BOOTLID CAMERA	Broken	883.50 FS	*350.00 FS
8	1		*REAR BOOTLID RH HINGE	Repair	235.00 FL	*- FL
9	1		*REAR BOOTLID LH HINGE	Repair	235.00 FL	*- FL
10	1		*REAR BOOTLID RH ABSORBER	Not Necessary	144.00 FL	*- FL
11	1		*REAR BOOTLID LH ABSORBER	Not Necessary	144.00 FL	*- FL
12	1		*REAR BOOTLID INNER TRIMBOARD	Not Necessary	490.00 FL	*- FL
13	1		*REAR BOOTLID INNER LOCK	Cut	190.00 FL	*190.00 FL
14	1		*REAR BOOTLID RUBBER	Twisted	220.00 FL	*220.00 FL
15	1		*REAR RH TAILLAMP	Cracked	640.00 FL	*640.00 FL
16	1		*REAR LH TAILLAMP	Cracked	640.00 FL	*640.00 FL
17	1		*REAR BUMPER	Torn	1,250.00 FL	*1,250.00 FL
18	4		*REAR BUMPER PARKING SENSOR	Damaged (3 PCS ONLY)	820.00 FL	*615.00 FL
19	1		*REAR BUMPER LOWER PAD	Deformed	445.00 FL	*445.00 FL
20	1		*REAR BUMPER LOWER CHROME MOULDING	Cracked	360.00 FL	*360.00 FL
21	1		*REAR BUMPER RH SIDE RETAINER	Broken	55.00 FL	*55.00 FL
22	1		*REAR BUMPER LH SIDE RETAINER	Broken	55.00 FL	*55.00 FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	410.00 FL	*410.00 FL
24	1		*REAR BUMPER REINFORCEMENT RH BRACKET	Bent	145.00 FL	*145.00 FL
25	1		*REAR BUMPER REINFORCEMENT LH BRACKET	Bent	145.00 FL	*145.00 FL
26	1		*REAR END PANEL (OUTER)	Bent	340.00 FL	*340.00 FL
27	1		*REAR END PANEL (INNER-TOP)	Bent	590.00 FL	*590.00 FL
28	1		*REAR END PANEL (INNER-LOWER)	Bent	620.00 FL	*620.00 FL
29	1		*REAR END PANEL TOP TRIM	Cut	125.00 FL	*125.00 FL
30	1		*REAR SPARE TYRE PANEL TOP COVER	Cut	630.00 FL	*630.00 FL
31	1		*REAR RH FENDER INNER TRIMBOARD	Torn	420.00 FL	*420.00 FL
32	1		*REAR LH FENDER INNER TRIMBOARD	Torn	420.00 FL	*420.00 FL
33	1		*REAR RH EXHAUST SILENCER BOX	Bent	2,550.00 FL	*2,550.00 FL
34	1		*REAR LH EXHAUST SILENCER BOX	Bent	2,550.00 FL	*2,550.00 FL
35	4		*REAR EXHAUST SILENCER CHROME COVER	Cut	1,280.00 FL	*1,280.00 FL
36	2		*REAR EXHAUST HEAT SHIELD	Buckled	210.00 FL	*210.00 FL
37	1		*REAR SPEAKER PANEL	Cracked	960.00 FL	*960.00 FL
38	1		*OVERROLL PROTECTION BEAM	Bent	6,900.00 FL	*6,900.00 FL
39	1		*AIRBAG SENSOR	Activated	305.00 FL	*305.00 FL
40	1		*AIRBAG ECU	Not Working	1,370.00 FL	*1,370.00 FL
41	1		*BATTERY AIRBAG SENSOR	Activated	74.00 FL	*74.00 FL
42	1		*FRONT RH SEAT BELT	Activated	390.00 FL	*390.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT LH SEAT BELT	Activated	390.00 FL	*390.00 FL
44	1		*SOFT TOP WITH REAR WINDSCREEN GLASS	Jammed	13,490.00 FS	*8,000.00 FS
45	1		*REAR NO PLATE	Scratched	40.00 FS	*40.00 FS
46	1		*REAR PARKING SENSOR WIRING	Cut	580.00 FS	*150.00 FS
47	1		*REAR RH AIR VENT COVER	Broken	70.00 FL	*70.00 FL
48	1		*REAR RH SEAT BELT	Activated	680.00 FL	*680.00 FL
49	1		*REAR LH SEAT BELT	Activated	680.00 FL	*680.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	47,034.50	39,128.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	1,602.05	1,529.40
Total Parts (\$\$)	45,432.45	37,598.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE SOFT TOP	New	800.00	500.00
2	TO REPLACE AIRBAG AND RESET AIRBAG SYSTEM	New	380.00	320.00
3	TO REPAIR DAMAGES	New	1,500.00	1,000.00
4	TO SPRAY PAINTING	New	1,500.00	1,200.00
Gross Labour Cost (\$\$)			4,180.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >