

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 04 Jan 2022

Preliminary Advice

Insured	: YN6584Y		
Vehicle No			
TP Vehicle No	: SBE3456Z	Accident Date	: 23/12/2021
Make	: AUDI S5 SPORTBACK	Assignment Date	: 28/12/2021
Date of Inspection	: 29/12/2021	Est. Duration of Repair	: 9
Inspection At	: VIN'S AUTO PTE LTD (VIN'S AUTO) SIN MING AUTOCITY,, 160 SIN MING DRIVE #03-03 SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,673.95
Revised Amount	:S\$	12,693.80
Check Items (Estimated)	:S\$	32,994.55
Total	:S\$	45,688.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.