

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

**Attention To :** China Taiping Insurance  
(Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

### Claim Details

**Case Ref. No. :** TP/122021/5144  
**Date :** 27-12-2021  
**Accident Date :** 23-12-2021

### Vehicle Details

**Make & Model :** Audi S5 CABRIOLET 3.0 TFSI  
QUATTRO  
**Chassis No :** WAUZZZ8F7BN007122  
**Registration No :** SBE3456Z

### Third Party Vehicle Details

**Registration No :** YN6584Y

| S/N | Description                                          | Qty  | Amount (\$\$)           |
|-----|------------------------------------------------------|------|-------------------------|
| 1   | REAR BOOTLID <i>BR</i>                               | 1.00 | \$2,420.00              |
| 2   | REAR BOOTLID EMBLEM <i>YAC</i>                       | 1.00 | \$95.00                 |
| 3   | REAR BOOTLID "S5" EMBLEM <i>YAC</i>                  | 1.00 | \$74.00                 |
| 4   | REAR BOOTLID THIRD BRAKE LIGHT <i>CRA</i>            | 1.00 | \$235.00                |
| 5   | REAR BOOTLID RH REFLECTOR <i>CRA</i>                 | 1.00 | \$520.00                |
| 6   | REAR BOOTLID LH REFLECTOR <i>CRA</i>                 | 1.00 | \$520.00                |
| 7   | REAR BOOTLID CAMERA <i>✓ BR</i>                      | 1.00 | \$930.00 <i>350(SN)</i> |
| 8   | REAR BOOTLID RH HINGE <i>X YAC</i>                   | 1.00 | \$235.00 <i>X</i>       |
| 9   | REAR BOOTLID LH HINGE <i>X</i>                       | 1.00 | \$235.00 <i>X</i>       |
| 10  | REAR BOOTLID RH ABSORBER <i>X</i>                    | 1.00 | \$144.00 <i>X</i>       |
| 11  | REAR BOOTLID LH ABSORBER <i>X</i>                    | 1.00 | \$144.00 <i>X</i>       |
| 12  | REAR BOOTLID INNER TRIMBOARD <i>X</i>                | 1.00 | \$490.00 <i>X</i>       |
| 13  | REAR BOOTLID INNER LOCK <i>Cut</i>                   | 1.00 | \$190.00                |
| 14  | REAR BOOTLID RUBBER <i>TR</i>                        | 1.00 | \$220.00                |
| 15  | REAR RH TAILLAMP <i>CRA</i>                          | 1.00 | \$640.00                |
| 16  | REAR LH TAILLAMP <i>CRA</i>                          | 1.00 | \$640.00                |
| 17  | REAR BUMPER <i>TN</i>                                | 1.00 | \$1,250.00              |
| 18  | REAR BUMPER PARKING SENSOR @ \$205.00 <i>DM 3PCS</i> | 4.00 | \$820.00 <i>615</i>     |
| 19  | REAR BUMPER LOWER PAD <i>RL</i>                      | 1.00 | \$445.00                |
| 20  | REAR BUMPER LOWER CHROME MOULDING <i>CRA</i>         | 1.00 | \$360.00                |
| 21  | REAR BUMPER RH SIDE RETAINER <i>✓ BR</i>             | 1.00 | \$55.00                 |
| 22  | REAR BUMPER LH SIDE RETAINER <i>✓ BR</i>             | 1.00 | \$55.00                 |
| 23  | REAR BUMPER REINFORCMENT <i>BT</i>                   | 1.00 | \$410.00                |
| 24  | REAR BUMPER REINFORCMENT RH BRACKET <i>✓ BT</i>      | 1.00 | \$145.00                |
| 25  | REAR BUMPER REINFORCMENT LH BRACKET <i>✓ BT</i>      | 1.00 | \$145.00                |
| 26  | REAR END PANEL (OUTER) <i>BT</i>                     | 1.00 | \$340.00                |
| 27  | REAR END PANEL (INNER - TOP) <i>✓ BT</i>             | 1.00 | \$590.00                |
| 28  | REAR END PANEL (INNER - LOWER) <i>✓ BT</i>           | 1.00 | \$620.00                |
| 29  | REAR END PANEL TOP TRIM <i>Cut</i>                   | 1.00 | \$125.00                |
| 30  | REAR SPARE TYRE PANEL TOP COVER <i>✓ CUT</i>         | 1.00 | \$630.00                |

# Vin's

**Vin's Motor Pte Ltd**  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

|    |                                               |       |      |                      |
|----|-----------------------------------------------|-------|------|----------------------|
| 31 | REAR RH FENDER INNER TRIMBOARD                | ✓ TN  | 1.00 | \$420.00             |
| 32 | REAR LH FENDER INNER TRIMBOARD                | ✓ TN  | 1.00 | \$420.00             |
| 33 | REAR RH EXHAUST SILENCER BOX                  | ✓ BT  | 1.00 | \$2,550.00           |
| 34 | REAR LH EXHAUST SILENCER BOX                  | ✓ BT  | 1.00 | \$2,550.00           |
| 35 | REAR EXHAUST SILENCER CHROME COVER @ \$320.00 | ✓ Act | 4.00 | \$1,280.00           |
| 36 | REAR EXHAUST HEAT SHIELD @ \$105.00           | ✓ BUC | 2.00 | \$210.00             |
| 37 | REAR SPEAKER PANEL                            | ✓ CRA | 1.00 | \$960.00             |
| 38 | OVERROLL PROTECTION BEAM                      | ✓ BT  | 1.00 | \$6,900.00 2500(SN)  |
| 39 | AIRBAG SENSOR                                 | ✓ ACT | 1.00 | \$305.00             |
| 40 | AIRBAG ECU                                    | ✓ NW  | 1.00 | \$1,370.00           |
| 41 | BATTERY AIRBAG SENSOR                         | ✓ ACT | 1.00 | \$74.00              |
| 42 | FRONT RH SEAT BELT                            | ✓ ACT | 1.00 | \$390.00             |
| 43 | FRONT LH SEAT BELT                            | ✓ ACT | 1.00 | \$390.00             |
| 44 | SOFT TOP WITH REAR WINDSCREEN GLASS           | ✓ JM  | 1.00 | \$14,200.00 4000(SN) |

\$45,741.00 22258  
(\$2,287.05)

Discount: -5%

\$43,453.95 21145.1

|    |                                           |        |      |                 |
|----|-------------------------------------------|--------|------|-----------------|
| 45 | REAR NO. PLATE                            | ✓ Scr. | 1.00 | \$40.00         |
| 46 | TO REMOVE AND REPLACE SOFT TOP            | ?      | 1.00 | \$800.00 500    |
| 47 | TO REPLACE AIRBAG AND RESET AIRBAG SYSTEM | ?      | 1.00 | \$380.00 320    |
| 48 | TO REPAIR DAMAGES                         |        | 1.00 | \$1,500.00 1000 |
| 49 | TO SPRAY PAINTING                         |        | 1.00 | \$1,500.00 1200 |

Subtotal w/o GST:

\$47,673.95

3060

32492.1

-20%: 26000

9 Days.

~~1/1~~

~~before part photos.~~

Gino Riamp

28/12/21

**LMS Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

**Vin's**

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 1999060676

**Estimated Cost of Repair  
(Supplementary)**

Attention To : China Taiping Insurance  
(Singapore) Pte Ltd  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

**Claim Details**

Case Ref. No. : TP/122021/5144  
Date : 27-12-2021  
Accident Date : 23-12-2021

**Vehicle Details**

Make & Model : Audi S5 CABRIOLET 3.0 TFSI  
QUATTRO  
Chassis No : WAUZZZ8F7BN007122  
Registration No : SBE3456Z

**Third Party Vehicle Details**

Registration No : YN6584Y

| S/N | Description                             | Qty  | Amount (\$) |         |
|-----|-----------------------------------------|------|-------------|---------|
| 1   | REAR PARKING SENSOR WIRING <i>✓ Cut</i> | 1.00 | \$580.00    | 150(SN) |
| 2   | REAR RH AIR VENT COVER <i>✓ BR</i>      | 1.00 | \$70.00     | ✓       |
| 3   | REAR RH SEAT BELT <i>✓ AS</i>           | 1.00 | \$680.00    | ✓       |
| 4   | REAR LH SEAT BELT <i>✓ AS</i>           | 1.00 | \$680.00    | ✓       |

Subtotal w/o GST: \$2,010.00

1430

-10%: 1287

Issued by Raymond Teo

This is a computer-generated document. No signature is required.