

## REPAIR ESTIMATE

LKK -

DATE: 27-Dec-21

INSURANCE: NTUC CLS

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: **SHA2253Z**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$430.90 <i>ly</i>
	Front Bumper Side Bracket LH	1		\$35.00 X <i>n7</i>
	Front Bumper Clips	10	\$2.20	\$22.00 X <i>n7</i>
	Front Fender LH	1		\$588.80 <i>ly</i>
	Front Fender Blue-Drive LH	1		\$26.60 <i>ly</i>
	Front Wheel Cap LH	1		\$346.40 X <i>n7</i>
	Front Bumper Grille LH	1		\$93.45 X <i>n7</i>
	SUB TOTAL		26.60	\$1,543.15
	LESS 20%		21.28	\$308.63
	DISCOUNTED PARTS TOTAL			\$1,234.52
	<u>Labour Charge</u>			
	Panel Beating			\$400.00 <i>350</i>
	Spray Painting		850	\$600.00 <i>500</i>
	Tuff Kote			\$40.00 X <i>n7</i>
	TOTAL LABOUR		871.28	\$1,040.00
	ESTIMATE TOTAL		2148.700 02 days #	\$2,274.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tammi 97495747  
'up' 27/12/21 C440

2 day 1

Resney after upon  
Lynch (Wharton)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

Date: \_\_\_\_\_