

COR I/s \$700 , 2 days.
red:1,574.52;69%

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK -

DATE: **27-Dec-21**

MODEL: **Hyundai Ioniq**

INSURANCE: **NTUC (L/S)**

VEHICLE NO.: **SHA2253Z**

MVA: **LIM T S**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$430.90 <i>ly</i>
	Front Bumper Side Bracket LH	1		\$35.00 <i>x</i>
	Front Bumper Clips	10	\$2.20	\$22.00 <i>x</i>
	Front Fender LH	1		\$588.80 <i>ly</i>
	Front Fender Blue-Drive LH	1		\$26.60 <i>ly</i>
	Front Wheel Cap LH	1		\$346.40 <i>x</i>
	Front Bumper Grille LH	1		\$93.45 <i>x</i>
	SUB TOTAL			\$1,543.15
	LESS 20%			\$308.63
	DISCOUNTED PARTS TOTAL			\$1,234.52
	Labour Charge			
	Panel Beating			\$400.00 <i>350</i>
	Spray Painting			\$600.00 <i>500</i>
	Tuff Kote			\$40.00 <i>x</i>
	TOTAL LABOUR			\$1,040.00
	ESTIMATE TOTAL			\$2,274.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Surphi 47495747
'up' 27/12/21 C440

2 days

Resurvey after repair
Surphi (Wharton)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 27.12.2021 10:51

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4155777

JO NO305499009

OMER

S COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

OUNT CARD NO.

REGN NO.:

SHA2253Z

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2..... F

MODEL

IONIQ(G2)

DATE/TIME IN 27.12.2021 08:30

YR OF MANU.

06.08.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU165139

COMPLETION DATE/TIME

JOB DESCRIPTION

Incident Date: 26.12.2021
TURE: 3P 26.12.2021/C

NO


0010

LABOR CODE

PB

DESCRIPTION

PANEL BEATING-SHA2253Z



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Jo.: SHA2253Z

LIMITS

Vehicle No.:

SHA2253Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard