COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

ÍATE:

27-Dec-21

MODEL:

Hyundai i40

VEHICLE NO .:

SHD3441A

MVA: LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	I The same of the state of the			
	Rear Bumper	1		\$553.004
	Rear Bumper Under Cover	1		\$228.00 de
	Rear Bumper Reinforcement	1		\$428.40 8X nn.
	Rear Bumper Clips	10	\$2.20	\$22.00 12
	Rear Bumper Reflector RH	1		\$32.00 ent
	Exhaust Muffler RH	1,		\$967.70 BOX NU
	SUB TOTAL		835	\$2,231.10
	LESS 20%	. ,		\$446.22
	DISCOUNTED TOTAL		668	\$1,784.88
	Reverse Sensors	1	, i	\$135.70 Knn
	SUB S/NETT			\$135.70
	LESS 10%		2	\$13.57
*	SUB S/NETT TOTAL		-	\$122.13
	Rear Fender Adv.Sticker RH / LH	1	\$100.00	\$200.00
	Rear Bumper Adv.Sticker	1	\$100.00	\$50.00
	Rear Bumper Mat	1		\$50.00
	NETT TOTAL		300	\$300.00
	SPARE RARES TOTAL		<i>y</i>	
	SPARE PARTS TOTAL			\$2,207.01
	Labour Charge			
	Panel Beating			\$300.00
	Spray Painting Charge		560	\$300.00 250
	R/I Reverse Sensors		760	A -
	R/I Exhaust System			\$120.00 \$ \$ 7
	TOTAL LABOUR		1528	\$840.00
	ESTIMATE TOTAL		2days	\$3,047.01

To resurvey before/after spray painting

• To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: