



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 9256S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT BUMPER	TO REPAIR SEE LABOUR	798.00	-
1	FRONT FENDER LH	* CHECK	698.00	-
1	FRONT FENDER COWLING	TORN	159.00	159.00
1	FRONT FENDER EMBLEM 'HYBRID'	NECESSARY	68.00	68.00
1	FRT LOWER ARM LH	NOT NECESSARY	581.00	-
1	FRT KNUCKLE ARM LH	NOT NECESSARY	587.00	-
1	FRT WHEEL BEARING LH	NOT NECESSARY	198.00	-
1	FRT WHEEL SHOCK ABSORBER LH	NOT NECESSARY	468.00	-
1	FRONT DOOR LH	BUCKLED	1,258.00	1,258.00
2	FRONT DOOR HINGES LH @\$68.00	NOT NECESSARY	136.00	-
1	FRONT DOOR WEATHERSTRIP LH	NOT NECESSARY	212.00	-
1	FRONT DOOR INNER LOCK LH	NOT NECESSARY	298.00	-
1	FRONT DOOR REGULATOR LH	NOT NECESSARY	698.00	-
1	FRONT DOOR INNER TRIM BOARD LH	NOT NECESSARY	598.00	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	651.00	-
1	SIDE SIRTING LH	CUT	898.00	898.00
	LESS 25% DISCOUNT		-2,076.50	-595.75
			6,229.50	1,787.25
<u>SPECIAL NETT ITEMS</u>				
1	SET FRT BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRT FENDER INNERSHIELD CLIP LH (SN)	NECESSARY	50.00	30.00
1	FRONT SPORTS RIM LH (SN)	TO REPAIR SEE LABOUR	80.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	180.00	-
			360.00	30.00
<u>LABOUR</u>				
	CHECK WIRING.		100.00	50.00
	R+R FRT FENDER QUARTER GLASS RH.	NOT NECESSARY	120.00	-
	CONDUCT WHEEL ALIGNMENT.		150.00	60.00

Report Ref No. CS/SMR21013228/Gqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIT UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	REALIGN HEADLAMP.	NOT NECESSARY	120.00	-
	KNOCK. INCLUSIVE OF THE REPAIR OF FRT BUMPER, REAR FENDER LH AND FRONT SPORTS RIM LH.		600.00	400.00
	SPRAY.		1,000.00	1,000.00
			2,490.00	1,510.00
GRAND TOTAL			9,079.50	3,327.25
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$523.50 NETT)				3,327.25

Report Ref No. CS/SMR21013228/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.