



MY CAR CONSULTANT PTE LTD

Reg no.: 2016058782

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-08 S737896

HP: 98888885

LKK Auto Consultants hence notify

the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• This party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed

• Complementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate No.

Date:

28/12/2021

Acknowledged by Repairer

SMN92565

Signature:

TOYOTA PRIUS

Date:

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRT BUMPER <i>X Repair</i>	1	\$ 798.00	\$ 798.00
2	FRONT FENDER LH <i>?</i>	1	\$ 698.00	\$ 698.00
3	FRONT FENDER COWLING <i>/ TN</i>	1	\$ 159.00	\$ 159.00
4	FRONT FENDER EMBLEM 'HYBRID' <i>/ NBC</i>	1	\$ 68.00	\$ 68.00
5	FRT LOWER ARM LH <i>X</i>	1	\$ 581.00	\$ 581.00
6	FRT KNUCKLE ARM LH <i>X</i>	1	\$ 587.00	\$ 587.00
7	FRT WHEEL BEARING LH <i>X</i>	1	\$ 198.00	\$ 198.00
8	FRT WHEEL SHOCK ABSORBER LH <i>X</i>	1	\$ 468.00	\$ 468.00
9	FRONT DOOR LH <i>/ m</i>	1	\$ 1,258.00	\$ 1,258.00
10	FRONT DOOR HINGES LH <i>X</i>	2	\$ 68.00	\$ 136.00
11	FRONT DOOR WEATHERSTRIP LH <i>X</i>	1	\$ 212.00	\$ 212.00
12	FRONT DOOR INNER LOCK LH <i>X</i>	1	\$ 298.00	\$ 298.00
13	FRONT DOOR INNER LOCK LH <i>X</i>	1	\$ 698.00	\$ 698.00
14	FRONT DOOR REGULATOR LH <i>X</i>	1	\$ 698.00	\$ 698.00
15	FRONT DOOR INNER TRIM BOARD LH <i>X</i>	1	\$ 598.00	\$ 598.00
16	REAR FENDER LH <i>X Repair</i>	1	\$ 651.00	\$ 651.00
	SIDE SKIRTING LH <i>/ cut</i>	1	\$ 898.00	\$ 898.00
	TOTAL PART			\$ 8,306.00
	LIST DOWN	25%		\$ 2,076.50
	AFTER LIST DOWN			\$ 6,229.50
	SPECIAL NETT			
1	FRT BUMPER CLIP SET <i>X NA</i>	1	\$ 50.00	\$ 50.00
2	FRT FENDER INNERSHIELD CLIP SET LH <i>/ NBC</i>	1	\$ 50.00	\$ 50.00
4	FRONT SPORTS RIM LH <i>X Repair</i>	1	\$ 800.00	\$ 800.00
5	FRONT TYRE LH <i>X NA</i>	1	\$ 180.00	\$ 180.00
	TOTAL AMOUNT			\$ 360.00
	LABOUR			
1	CHECK WIRING	1	\$ 100.00	\$ 100.00
2	R+R FRT FENDER QUARTER GLASS RH	1	\$ 120.00	\$ 120.00
3	CONDUCT WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00
4	REMOVE AND REFIT UNDERCARRIAGE	1	\$ 400.00	\$ 400.00
5	REALIGN HEADLAMP	1	\$ 120.00	\$ 120.00
6	KNOCK	1	\$ 600.00	\$ 600.00
7	SPRAY	1	\$ 1,000.00	\$ 1,000.00
	TOTAL AMOUNT			\$ 2,490.00
	Parts Replacement Amount			\$ 6,589.50
	Total Amount for Labour			\$ 2,490.00
	Total Amount			\$ 9,079.50

5 Days. Lumpsum Repair Quoting
After repair Photos. 88888882
27/12/21

30

50
X NA
60
X
X } m
400
/