



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	:	UC293
Vehicle No.	:	SKU8870L
Make & Model	:	MERCEDES BENZ E200 CGI A

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<b><u>LABOUR</u></b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	1000
3	To carried out repair on rear chassis member LH/RH	300.00	200
4	Remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	100.00	100
5	Airbag ECU resets and programming	300.00	150
6	To carried out repair on connector and wiring system at accident damaged area and check for all electrical proper function	100.00	50
7	Remove and replace undercarriage LH	200.00	?
8	Remove and replace front cross member	300.00	X
9	Remove and refit engine to facilitate repair	500.00	?
10	Abs System coding and programming	300.00	180 ?
<b>Labour Total :</b>		<b>4700.00</b>	
<b>TOTAL (PARTS &amp; LABOUR):</b>		<b>35351.20</b>	

Steve (LKK) 21.12.21, 12.30pm

W/P

L/S

12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_