

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1055/2021/JT
DATE : 27-Dec-21
WIP : 60344

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 29/12/21

YOUR INSURED VEH NO : SMV 6275 P

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Motor Claims Dept

Tel: 6389 6541 - Fax: 6224 7175

Hi Adrian,

5 days - ok - Jy - 01 Mar 22

OWNER'S NAME : MR SUBRAMANIAN BHASKARAN
ADDRESS : BLK 636 JURONG WEST STREET 65
#14-352
SINGAPORE 640636
TELEPHONE : HP +65 97366463
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00899931
VEHICLE NO : **SLA 4432 M**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 29/2/2016
ENGINE NO : CZC 507710
CHASSIS NO : WAUZZZ8V4G1056445
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Dec-21
PLACE OF ACCIDENT : JURONG WEST STREET 61

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 4432 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	600.00	
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N \$	400.00	
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
5	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
SUB TOTAL LABOUR CHARGES			\$ 4,280.00	\$ 280.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLA 4432 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
			\$ 280.00
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	\$ 2,100.00
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$ 4,500.00	\$ 1,400.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 13,872.00	\$ 3,972.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 4432 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,070.00	\$ 2,070.00
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 32.00	
4	REAR BUMPER SPOILER	1	\$ 237.00	
5	REAR LIGHT REFLECTOR - RH	1	\$ 41.00	
6	TAIL LIGHT - RH	1	\$ 877.00	
7	TAIL LIGHT TRIM - RH	1	\$ 30.00	
8	REAR BUMPER GUIDE SECTION OUTER - RH	1	\$ 67.00	\$ 66.20
9	REAR FENDER - RH	1	\$ 4,140.00	
10	REAR WINDSCREEN	1	\$ 814.00	
11	QUARTER WINDOW	1	\$ 570.00	
12	PRIMER	2	\$ 40.00	
13	REAR WHEEL HOUSING LINER	1	\$ 240.00	
14	REAR WHEEL SPOILER - RH	1	\$ 35.00	
15	REAR WHEEL SPOILER COVER - RH	1	\$ 4.00	
16	FUEL FILLER	1	\$ 89.00	
17	ARYLIC SEALANT	S/N	\$ 180.00	
18	CAVITY WAX	S/N	\$ 140.00	
19	STONE CHIP	S/N	\$ 180.00	
20	METAL FILLER POWDER	S/N	\$ 280.00	
SUB TOTAL SPARE PARTS			\$ 10,259.00	\$ 2,136.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLA 4432 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
				\$ 2,136.20
21	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
22	1/4 GLASS SEALANT	S/N	\$ 100.00	
23	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 10,959.00	\$ 2,136.20
TOTAL LABOUR CHARGES		:	\$ 13,872.00	\$ 3,972.00
GRAND TOTAL		:	\$ 24,831.00	\$ 6,108.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT