

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21013241/GQY3N2**Date:** 17/03/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00133812100		
<b>Claimant Vehicle No :</b>	SLW8176K	<b>Insured Vehicle No :</b>	SJH1289S		
Date of Loss:	24/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207584/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLW8176K</b>	Engine No:	P520486006
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8J0193936
Reg. Date:	01/03/2018 (Man. Year: 2017)	Odometer:	59595 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,784.08	2,206.48	577.60	20.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	800.00	660.00	45.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,244.08</b>	<b>3,006.48</b>	<b>1,237.60</b>	<b>29.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>(S\$)</b>	4,244.08	2,400.00	1,844.08	43.45
<b>+ GST 7.00/7.00% (S\$)</b>	297.09	168.00	129.09	43.45
<b>Nett Amount (S\$)</b>	<b>4,541.17</b>	<b>2,568.00</b>	<b>1,973.17</b>	<b>43.45</b>

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	29/12/2021	Inspected At: Vin's Auto Pte Ltd (Vin's Auto) Sin Ming AutoCity,, 160 Sin Ming Drive #03-03 Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 16 Mar 2022)**Parts:** 143      MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLW8176K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILLAMP	Cracked	534.90 FL	*534.90 FL
2	1		*REAR BUMPER	Torn	1,128.60 FL	*1,128.60 FL
3	1		*REAR BUMPER LH TOWING COVER	Missing	18.00 FL	*18.00 FL
4	1		*REAR BUMPER LH REFLECTOR	Not Necessary	53.60 FL	*- FL
5	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	38.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	564.20 FL	*564.20 FL
7	10		*REAR BUMPER CLIPS	Necessary	59.00 FL	*59.00 FL
8	1		*REAR END PANEL	Repair	530.40 FL	*- FL
9	1		*REAR END PANEL TOP TRIM	Cut	89.70 FL	*89.70 FL
10	1		*REAR BOOTLID RUBBER	Twisted	113.70 FL	*113.70 FL
11	1		*REAR BUMPER PARKING SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,410.10</b>	<b>2,708.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	626.02	501.62
<b>Total Parts (\$)</b>	<b>2,784.08</b>	<b>2,206.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR DAMAGES	New	680.00	400.00
2	TO SPRAY PAINTING	New	780.00	400.00
			<b>Gross Labour Cost (S\$)</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >