

# Vin's

Vin's Motor Pte Ltd  
160 Sin Ming Drive  
#03-03 Sin Ming Autocity  
Singapore 575722  
Tel : 6453 2121 Fax : 6459 9795  
GST Registration No. 199906067G

## Estimated Cost of Repair

Attention To : **China Taiping Insurance (Singapore) Pte Ltd**  
3 Anson Road  
#15-00 Springleaf Tower  
Singapore 079909

### Claim Details

Case Ref. No. : TP/122021/5146  
Date : 27-12-2021  
Accident Date : 24-12-2021

### Vehicle Details

Make & Model : Mazda MAZDA3 SEDAN 1.5 AT EU6  
Chassis No : JM6BN22A8J0193936  
Registration No : SLW8176K

### Third Party Vehicle Details

Registration No : SJH1289S

S/N	Description	Qty	Amount (\$\$)
1	REAR LH TAILLAMP / CRA	1.00	\$534.90
2	REAR BUMPER / TN	1.00	\$1,128.60
3	REAR BUMPER LH TOWING COVER / mis	1.00	\$18.00
4	REAR BUMPER LH REFLECTOR X / YNN	1.00	\$53.60
5	REAR BUMPER LH SIDE RETAINER X / BT	1.00	\$38.00
6	REAR BUMPER REINFORCEMENT /	1.00	\$564.20
7	REAR BUMPER CLIPS @ \$5.90 / dcl	10.00	\$59.00
8	REAR END PANEL X Repair	1.00	\$530.40
9	REAR END PANEL TOP TRIM / cut	1.00	\$89.70
10	REAR BOOTLID RUBBER / twi	1.00	\$113.70
			\$3,130.10
Discount: -20%			(\$626.02)
			\$2,504.08
11	REAR BUMPER PARKING SENSOR / JM	1.00	\$280.00 200
12	TO REPAIR DAMAGES	1.00	\$680.00 400
13	TO SPRAY PAINTING	1.00	\$780.00 400

Subtotal w/o GST: \$4,244.08

4 days  
4/5  
After repair photo.  
Gmo @ 29/12/21

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: