

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

## Estimated Cost of Repair

**Attention To :** China Taiping Insurance  
 (Singapore) Pte Ltd  
 3 Anson Road  
 #15-00 Springleaf Tower  
 Singapore 079909

**Claim Details**  
**Case Ref. No. :** TP/122021/5146  
**Date :** 27-12-2021  
**Accident Date :** 24-12-2021

### Vehicle Details

**Make & Model :** Mazda MAZDA3 SEDAN 1.5 AT  
 EU6  
**Chassis No :** JM6BN22A8J0193936  
**Registration No :** SLW8176K

**Third Party Vehicle Details**  
**Registration No :** SJH1289S

S/N	Description	Qty	Amount (\$\$)
1	REAR LH TAILLAMP / CRA	1.00	\$534.90 ✓
2	REAR BUMPER / TN	1.00	\$1,128.60 ✓
3	REAR BUMPER LH TOWING COVER / mis	1.00	\$18.00 ✓
4	REAR BUMPER LH REFLECTOR X Linn	1.00	\$53.60
5	REAR BUMPER LH SIDE RETAINER X BT	1.00	\$38.00
6	REAR BUMPER REINFORCEMENT / BT	1.00	\$564.20 ✓
7	REAR BUMPER CLIPS @ \$5.90 / del	10.00	\$59.00 ✓
8	REAR END PANEL X Repair	1.00	\$530.40
9	REAR END PANEL TOP TRIM / cut	1.00	\$89.70 ✓
10	REAR BOOTLID RUBBER / twi	1.00	\$113.70 ✓
			<hr/>
			\$3,130.10 2508.1
<b>Discount: -20%</b>			(\$626.02)
			<hr/>
			2006.48
			\$2,504.08
11	REAR BUMPER PARKING SENSOR / PM	1.00	\$280.00 200
12	TO REPAIR DAMAGES	1.00	\$680.00 400
13	TO SPRAY PAINTING	1.00	\$780.00 400

**Subtotal w/o GST:** \$4,244.08  
 3006.48  
 20%: 2400

4 days  
 4/5  
 After repair photo.  
 Gmo @ 29/12/21

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: